
Submit 1 Copy To Appropriate District State of New Mexico Office	Form C-103
District I – (575) 393-6161 Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240	Revised August 1, 2011 WELL API NO.
District II - (575) 748-1283	30-025-30536
811 S. First St., Artesia, NM 88210OIL CONSERVATION 2000 ConservationDistrict III - (505) 334-61781220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV - (505) 476-3460 Santa Fe, NM 81/50/50 9 2018	STATE X FEE 6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	LG-6346
SUNDRY NOTICES AND REPORTS ON WELES CEIVED (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well X Gas Well Other	 7. Lease Name or Unit Agreement Name STATE 12 "AA" 8. Well Number
2. Name of Operator	9. OGRID Number
CIMAREX ENERGY CO. OF COLORADO	162683
3. Address of Operator 600 N. MARIENFELD, SUITE 600, MIDLAND, TEXAS 79701	10. Pool name or Wildcat LOVINGTON PENN, N.E.
4. Well Location	
Unit Letter I : 1980 feet from the SOUTH line and 810 feet from the EAST line	
Section 12 Township 16S Range	36E NMPM LEA County
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3,868' – GR	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING	
PULL OR ALTER CASING	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of	
proposed completion or recompletion. Ressure Test CSg.	
1) SET 5-1/2" CIBP @ 11,400'; CIRC. WELL W/ M.L.F.; PUMP 30 SXS. CMT. @ 11,400'-11,160' (T/STWN.).	
2) PUMP 25 SXS. CMT. @ 9,765'-9,575' (T/W.C.).	
 PUMP 45 SXS. CMT. @ 8,510'-8,224' (T/ABO, 5-1/2" DV TOOL); WOC X TAG CMT. PLUG. PUMP 25 SXS. CMT. @ 6,530'-6,370' (T/GLOR.). 	
5) PUMP 65 SXS. CMT. @ 5,075'-4,611' (T/S.A., 8-5/8" CSG.SHOE); WOC X TAG CMT. PLUG.	
6) PUMP 25 SXS. CMT. @ 3,332'-3,202' (T/YATES, B/SALT); WOC X TAG CMT. PLUG.	
 PUMP 25 SXS. CMT. @ 2,290'-2,114' (T/SALT, T/ANHY.); WOC X TAG CMT. PLUG. MIX X CIRC. TO SURF. 55 SXS. CMT. @ 450'-3'. 	
9) DIG OUT X CUT OFF WELLHEAD 3' B.G.L.; WELD ON STEEL PLATE TO CSGS. X INSTALL DRY HOLE MARKER.	
	See Attached
Spud Date: Rig Release Date:	
	Conditions of Approval
	•••
I hereby certify that the information above is true and complete to the best of my knowled	ge and belief.
SIGNATURE SIGNATURE AGENT	DATE: 11/06/18
Type or print name: DAVID A. EYLER E-mail address: DEYLER@MILAGRO-RES.COM PHONE: 432.687.3033	
For State Use Only	
APPROVED BY: Markethilter TITLE P.E.S. Conditions of Approval (if any):	DATE 11/13/2018



Cimarex Energy Co. of Colorado CIMAREX KB : 21' above GL State AA 12 #1 1980' FSL & 810' FEL Sec. 12, T-16-S, R-36-E, Lea Co., NM A. Santiago 30-025-30536 02/26/2015 CERC. 55 \$x 5.@ 450 - 3 T/ANHY. - 2,KH 13-3/8", 61# H-40 csg @ 400' T/ SALT. ~ 2,230 cmtd w/ 490 sx, cmt circ 7/ YATES - 3,267 Pump 25 5× 5. @ 2,290 -2,114 - 196 T/ 5.A. ~ 5,000' Pump 25 5x 5 3,332 - 3,202-MG T/GLOR. - 6,450 TIABO ~ 8,430' -Dump 65 5×5- 5,075 - 4,611 - TAG T/mc. - 9,670' 8-5/8", 32# J-55 csg @ 4686' cmtd w/ 1820 sx T/ PENNL - 10,630 T/SRIN. - 11,384 M.h.F. Pump 255×4.0 6,530'-6,370' pakf. DV Tool @ 8309', cmt w/ 1280 sx, cmt circ. - Pump 455×5.08,510'-8,224-MC-M.L.F. - Pump 25 \$* 5.09,765 - 9,575! M.L.F. Pump 30 5x = 0 11,400'-11,160' -SET 5-1/2" CJERGE 11, 400 ' Strawn perfs (11443' - 11512') CIBP @ 11562' Strawn perfs (11572' - 11578') PBTD @ 11840' 5-1/2" 17 & 20# L-80 @ 11930' cmtd w/ 1200 sx, cmt circ TD @ 11930' N. Pularlin Printed 11/6/2018

GENERAL CONDITIONS OF APPROVAL:

- 1) Insure all bradenheads have been exposed, identified, and valves are operational prior to rigging up on well.
- 2) Contact the appropriate NMOCD District Office no later than 24 hours prior to moving in and rigging up.
- 3) A copy of the approved C103 intent to P&A should be distributed to the onsite company and plugging representatives. Approved procedures are good for a period of one year from approved date, unless otherwise specified on the C103 intent. Approvals past this date will require the submission and approval of a new C103 intent.
- 4) A company representative is required to be present to witness all operations including setting CIBP's, circulation of mud laden fluids, perforating, squeezing or spotting cement plugs, tags, or any other operations approved on the C103 intent to P&A. Company representative should contact the NMOCD and report all operations.
- 5) Any changes that may be required during plugging operations should be approved by the NMOCD before proceeding.
- 6) A closed loop system is to be used for all plugging operations. Contents of the steel pits to be hauled to a NMOCD permitted disposal facility.
- 7) Mud laden fluids must be placed between all cement plugs mixed at 25 sacks of salt gel per 100 barrels of brine.
- 8) All cement plugs will be 100' or 25 sacks cement, whichever is greater. Class 'C' cement will be used above 7500' and Class 'H' below 7500'.