

Submit 1 Copy To Appropriate District Office

District I - (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II - (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III - (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87416  
District IV - (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised August 1, 2011

**HOBBS OGD CONSERVATION DIVISION**  
1220 South St. Francis Dr.  
Santa Fe, NM 87505  
DEC 05 2018

WELL API NO. 30-025-07588
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. N/A
7. Lease Name or Unit Agreement Name South Hobbs (G/SA) Unit
8. Well Number 036
9. OGRID Number: 157984
10. Pool name or Wildcat: Hobbs (G/SA)

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☒ Other Injector

2. Name of Operator  
Occidental Permian Ltd.

3. Address of Operator  
P.O. Box 4294, Houston, Tx 77210

4. Well Location (Surface)

Unit Letter F 1980 feet from the North line and 1980 feet from the West line

Section 3 Township 19S Range 38E NMPM Lea County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)  
3617' (DF)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- 1) MIRU PU. ND Wellhead. NU BOP.
- 2) POOH with Inj. Equipment
- 3) Squeeze 4067'-4161'
- 4) Drill out squeeze
- 5) Perforate 4150'-4160'
- 6) Acid treat open hole and 4150-4160'
- 7) RIH injection equipment
- 8) ND BOP. NU Wellhead. RDMO PU

During this procedure we plan to use the closed-loop system with a steel tank and haul contents to the required disposal per ODC Rule 19.15.17

**Condition of Approval: notify**

**OCD Hobbs office 24 hours**

**prior of running MIT Test & Chart**

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juf TITLE Production Engineer DATE 12/04/2018

Type or print name Jake Perry E-mail address: Jake\_Perry@oxy.com PHONE: 713-215-7546

For State Use Only

APPROVED BY: Maky Brown TITLE NO/I DATE 12/5/2018

Conditions of Approval (if any):

	<b>City of Hobbs</b> <b>Municipal Code Section 8.44.050</b> <b>(Existing Well Permit)</b> <b>Application</b>	
<b>Date:</b>	12/04/2018	
<b>Operator:</b>	Oxy Permian Ltd.	
<b>Lease Name:</b>	South Hobbs Unit	
<b>Well Name:</b>	036	
<b>Well Location:</b>	Section 3, U.L. "F" 1980' FNL & 1980' FWL Township 19S; Range 38-E	
<b>Estimated Rig Up Date:</b>	01/25/2018 – 02/14/2018	
<b>Surface equipment add/change:</b>	None	
<b>Description of Procedure:</b>	MIRU PU, NDWH, NUBOP POOH with Inj. Equipment Squeeze 4024'-4161' Drill out squeeze Perforate 4150'-4160' Acid treat open hole and 4150-4160' RIH injection equipment ND BOP. NU Wellhead. RDMO PU	
<b>Attachment(s):</b>		
<b>NMOCD Form</b>		
<b>Traffic Control Plan</b>		
<b>Local Oxy Contact:</b>	Alfredo Ceniceros	806-215-2385 (day time)
	Josh Schut	701-690-7053 (day time)
	Glen Hubbard	575-631-6881 (day time)
	Oxy Control Room	575-391-4727 (after hours)