

Submit I Copy To Appropriate District	State of New Mexico	Form C-103
Office	Energy, Minerals and Natural Resources	Revised July 18, 2013
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources	WELL API NO.
District II - (575) 748-1283	OIL CONSERVATION DIVISION	30-025-36495
811 S. First St., Artesia, NM 88210 District III – (505) 334-6178	1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505	STATE FEE
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Santa Pe, NWI 87505	6. State Oil & Gas Lease No.
87505		
	CES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
	ALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A ATION FOR PERMIT" (FORM C-101) FOR SUCH	Fee MA B
PROPOSALS.)		8. Well Number #5
	Gas Well Other HOBBS OCD	
2. Name of Operator Mack Energy Corporation		9. OGRID Number 013837
3. Address of Operator	DEC 042018	10. Pool name or Wildcat
P.O. Box 960 Artesia,NM 88210		Maljamar; Graburg-San Andres
4. Well Location	RECEIVED	
Unit Letter H :	2310 feet from the <u>N</u> line and	330 feet from the E line
Section 31	Township 17S Range 33E	NMPM County Lea
	11. Elevation (Show whether DR, RKB, RT, GR, et	
	3991' GR	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO:		
	PLUG AND ABANDON	BSEQUENT REPORT OF:
		RILLING OPNS. P AND A
OTHER:		
	eted operations. (Clearly state all pertinent details, a	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		
proposed completion of recompletion.		
1. Set 5 ½" CIBP @ 4800'. Pressure test csg. Circulate hole w/ MLF. Spot 25 sx cmt @ 4800-4650'.		
2. Perf & Sqz 50 sx cmt @ 2650-2450'. WOC & Tag (Yates & 8 5/8" Shoe)		
3. Spot 25 sx cmt @ 1600-1450'. WOC & Tag (T/Salt)		
	6-256', WOC & Tag (13 3/8" Shoe)	
5. S pot 25 sx cmt @ 100' to surf ace. TO SURFACE 6. Cut off well head, verify cmt to surface, weld on Dry Hole Marker.		
6. Cut off well head, verify cr	in to surface, weld on Dry Hole Marker.	See Attached
		Conditions of Approval
		j
Spud Date:	Rig Release Date:	
I hereby certify that the information a	bove is true and complete to the best of my knowled	lge and belief.
1 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0 -		
SIGNATURE Alogael Manigomerica) TITLE Agent DATE 12/04/2018		
Type or print name Abigail Montgomery E-mail address: PHONE: 432-580-7161		
APPROVED BY	tritale_TITLE P.E.S.	DATE 12/04 12018
Conditions of Approval (if any):		

m



.



GENERAL CONDITIONS OF APPROVAL:

- 1) Insure all bradenheads have been exposed, identified, and valves are operational prior to rigging up on well.
- 2) Contact the appropriate NMOCD District Office no later than 24 hours prior to moving in and rigging up.
- 3) A copy of the approved C103 intent to P&A should be distributed to the onsite company and plugging representatives. Approved procedures are good for a period of one year from approved date, unless otherwise specified on the C103 intent. Approvals past this date will require the submission and approval of a new C103 intent.
- 4) A company representative is required to be present to witness all operations including setting CIBP's, circulation of mud laden fluids, perforating, squeezing or spotting cement plugs, tags, or any other operations approved on the C103 intent to P&A. Company representative should contact the NMOCD and report all operations.
- 5) Any changes that may be required during plugging operations should be approved by the NMOCD before proceeding.
- 6) A closed loop system is to be used for all plugging operations. Contents of the steel pits to be hauled to a NMOCD permitted disposal facility.
- 7) Mud laden fluids must be placed between all cement plugs mixed at 25 sacks of salt gel per 100 barrels of brine.
- 8) All cement plugs will be 100' or 25 sacks cement, whichever is greater. Class 'C' cement will be used above 7500' and Class 'H' below 7500'.