Submit 1 Copy To Appropriate District	State of New Mexico	Form C-103		
Office <u>District I</u> – (575) 393-6161	Energy, Minerals and Natural Resour	rces Revised August 1, 2011		
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283		WELL API NO. 30-025-30007		
811 S. First St., Artesia, NM 88210	11 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION			
District III – (505) 334-6178 1000 Rio Brazos Rd., Aztec, N	1220 South St. Francis Dr.	5. Indicate Type of Lease STATE FEE		
<u>District IV</u> = (303) 470-3400	S 000 Santa Fe, NM 87505	6. State Oil & Gas Lease No.		
1220 S. St. Francis Dr., Santa Fe, NM 87505 DFC 1	7 2018	313857		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE TO THE PROPOSALS.)		7. Lease Name or Unit Agreement Name WEST DOLLARHIDE QUEEN SAND UNIT		
1. Type of Well: Oil Well	as Well Other	8. Well Number 84		
2. Name of Operator RAM ENERGY LLC	/	9. OGRID Number 309777		
3. Address of Operator 2100 S. UTICA AVE., SUITE 17	5, TULSA, OK 74114	10. Pool name or Wildcat DOLLARHIDE QUEEN (018810)		
4. Well Location				
Unit LetterL:1	000feet from theWEST line ar	nd2300feet from theSOUTHline		
Section 29	Township 24S Range	38E NMPM LEA County		
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3199.5' KB				
12. Check Ap	opropriate Box to Indicate Nature of N	Notice, Report or Other Data		
NOTICE OF INT	ENTION TO:	SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIA	AL WORK ALTERING CASING		
 -	<u> </u>	ICE DRILLING OPNS. P AND A		
PULL OR ALTER CASING DOWNHOLE COMMINGLE	MULTIPLE COMPL CASING/	CEMENT JOB		
DOWNHOLE COMMININGLE				
OTHER:	OTHER:			
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date				
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
• • •	-			
1. NOTIFY NMOCD 24 HRS. I	BEFORE MIRU.			
2. MIRU. ND WH, NU BOPE.				
 SET CIBP@3600' AND SPOT 25SX OF CLASS "C" CEMENT FROM 3650'-3300'. (PERFS) CIRCULATE 9.5 PPG MLF AND TEST CASING. 				
5. SPOT 40SX OF CLASS "C"	CEMENT FROM 2844'-2515'. WOC&TAC			
	CEMENT FROM 1326'-1236'. WOC&TAC			
 SPOT 55SX OF CLASS "C" CEMENT FROM 484'-SURFACE. VERIFY CEMENT TO SURFACE. (FW/SHOE/SURFACE). CUTOFF WELLHEAD, ANCHORS 3' BELOW SURFACE AND INSTALL DRYHOLE MARKER. TURN OVER FOR 				
RECLAMATION.	4" dia 4' Tall Above			
CLOSED LOOP CONTAINS	MENT SYSTEM WILL BE USED FOR FLU	MDC		
<u></u>		See Aftached Conditions of Approval		
Spud Date:	Rig Release Date:	See Affaction and		
Spud Date.	Nig Release Date.	of Appro		
		Couglinging		
I hereby certify that the information at	ove is true and complete to the best of my ki	nowledge and belief.		
,	•	-		
SIGNATURE MI-NO	TITLE OPERATION	IS MANAGERDATE12/11/18		
•		I@RAMENERGY.NET PHONE: _(918)947-6301_		
For State Use Only				
APPROVED BY: Kenny Fort	ner TITLE Compliance	Officer A DATE 12-27-18		
Conditions of Approval (if any):				

WELLBORE DIAGRAM WEST DOLLARHIDE QUEEN SAND UNIT #84

CHERTAL

Field: Q	By: LEE R. By: DE QUEEN SAND UNIT UEEN L & 2300' FSL St.: NM	Well #: API Unit Ltr.: TSHP/Rng: Pool Code: Directions:	84 30-025-30007 L Sec. 29 24S-T38E OGRID: 309777
Surface Casing Size: 8-5/8" Wt., Grd.: 24# Depth: 434' Sxs Cmt: 250 Circulate: yes TOC: surface Hole Size: 12-1/4"			
FORMATION TOPS T.Salt 1276' B. Salt 2615'			
Intermediate Casing Size: 5-1/2" Wt., Grd.: 15.5#/17# Depth: 3983' Sxs Cmt: 1000 Circulate: yes TOC: surface		Que	en: 3734'-3880'(OA)

7-7/8"

Hole Size:

WELLBORE DIAGRAM WEST DOLLARHIDE QUEEN SAND UNIT #84

(Page 6550) Created: 12/11/18 By: LEE R. Well #: 84 Updated: By: API 30-025-30007 Lease: WEST DOOLARHIDE QUEEN SAND UNIT Unit Ltr.: L Sec. 29 QUEEN TSHP/Rng: 24S-T38E Field: OGRID: 1000' FWL & 2300' FSL Pool Code: 309777 Surf. Loc.: Bot. Loc.: County: St.: NM Directions: LEA Status: Surface Casing Size: 8-5/8" Wt.. Grd.: 24# Depth: 434 Sxs Cmt: 250 Circulate: yes TOC: surface Hole Size: 12-1/4" SPOT 55SX OF CMT FROM 484'-SURFACE. VERIFY. (FW/SHOE/SURFACE) MLF SPOT 25SX OF CMT FROM 1326'-1236'. WOC&TAG. (T.SALT) **MLF** FORMATION TOPS T.Salt 1276' SPOT 40SX OF CMT FROM 2844'-2515'. B. Salt 2615' MLF WOC&TAG. (YATES/B.SALT) SET CIBP@3650' AND SPOT 25SX ON TOP Intermediate Casing FROM 3650'-3300'.(PERFS) Size: 5-1/2" Queen: 3734'-3880'(OA) Wt., Grd.: 15.5#/17#

Depth:

TOC:

Sxs Cmt:

Circulate:

Hole Size:

3983'

1000

yes

surface

7-7/8"

GENERAL CONDITIONS OF APPROVAL:

- 1) Insure all bradenheads have been exposed, identified, and valves are operational prior to rigging up on well.
- 2) Contact the appropriate NMOCD District Office no later than 24 hours prior to moving in and rigging up.
- 3) A copy of the approved C103 intent to P&A should be distributed to the onsite company and plugging representatives. Approved procedures are good for a period of one year from approved date, unless otherwise specified on the C103 intent. Approvals past this date will require the submission and approval of a new C103 intent.
- 4) A company representative is required to be present to witness all operations including setting CIBP's, circulation of mud laden fluids, perforating, squeezing or spotting cement plugs, tags, or any other operations approved on the C103 intent to P&A. Company representative should contact the NMOCD and report all operations.
- 5) Any changes that may be required during plugging operations should be approved by the NMOCD before proceeding.
- 6) A closed loop system is to be used for all plugging operations. Contents of the steel pits to be hauled to a NMOCD permitted disposal facility.
- 7) Mud laden fluids must be placed between all cement plugs mixed at 25 sacks of salt gel per 100 barrels of brine.
- 8) All cement plugs will be 100' or 25 sacks cement, whichever is greater. Class 'C' cement will be used above 7500' and Class 'H' below 7500'.