HOBBS OCD DEC 21 2018

Submit One Copy To Appropriate District	State of New M	Mexico .	م و المحمد ال	7	Form C-103	
Office	Energy, Minerals and Natural Resources		aeceive!	ال   Revised	November 3, 2011	
<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240	2B), 1.1		WELL API NO	),		
District II 811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION			30-025-28230			
District III 1220 South St. Francis Dr			5. Indicate Type of Lease			
1000 Rio Brazos Rd., Aztec, NM 87410			STATE FEE 6. State Oil & Gas Lease No.			
District IV 1220 S. St. Francis Dr., Santa Fe, NM			L-3001	Jas Lease I	10.	
87505						
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit Agreement Name			
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			NORT	NORTHEAST KEMNITZ		
PROPOSALS.)  1. Type of Well: Oil Well X Gas Well Other			8. Well Number #8			
2. Name of Operator MATADOR PRODUCTION COMPANY			9. OGRID Number			
MATADOR PRODUCTION COMPANY			228937			
3. Address of Operator 5400 LBJ FREEWAY, SUITE 1500			10. Pool name or Wildcat			
DALLAS TX 75240			KEMNITZ; MORROW (GAS)			
4. Well Location						
Unit Letter K: 1980 feet from the SOUTH line and 1980 feet from the WEST line						
Section 16 Township 16S Range 34E NMPM County LEA						
11. Elevation (Show whether DR, RKB, RT, GR, etc.)						
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data						
NOTICE OF INT	ENTION TO:	1 SUB	SEQUENT R	FPORT	OE.	
	PLUG AND ABANDON	REMEDIAL WOR			NG CASING	
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS.☐ P AND A ☐						
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN	T JOB 🔲		,	
	_	<b>  53.</b>			1500	
OTHER:     Description   Location is ready for OCD inspection after P&A						
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.						
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the						
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR						
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.						
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and						
other production equipment.  ☑ Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.						
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with						
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed						
from lease and well location.						
All metal bolts and other materials	have been removed. Portable	bases have been remo	oved. (Poured ons	ite concrete	bases do not have	
to be removed.)  All other environmental concerns have been addressed as per OCD rules.						
All other environmental concerns have been addressed as per OCD rules.  Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-						
retrieved flow lines and pipelines.				· ·	2011 11011	
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well						
focation, except for utility's distribution	n infrastructure.					
When all work has been completed, return this form to the appropriate District office to schedule an inspection.						
1 , 1						
SIGNATURE	TITLE	ENGIN	EER	DATE_	12/7/18	
TYPE OR PRINT NAME CHRIS	VII.I.ARREAI. E BAAI	L: CVILLARREAL@MATA	DORRESOURCES COM	рисьте.	(972) 371 -5471	
For State Lise Only						
ADDROVED BY	4.17.	Connolina	2005.	0	17-11-18	