
Office	State of New Mexico			Form C-103		
District I – (575) 393-6161 Energy, Minerals and Natural Resources			Revised July 18, 2013 WELL API NO.			
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> - (575) 748-1283			30-025-40890			
11 S. First St., Artesia, NM 88210 UIL CONSERVATION			5. Indicate Type			
District III – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410			STATE			
Nanta Bey NIVLX (SUN			6. State Oil & Ga	s Lease No.		
1220 S. St. Francis Dr., Santa Fe, NM 87505						
SUNDRY NOTICES AND REPORTS ON WELLS				r Unit Agreement Nam	ne	
District IV - (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR FOR BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			Gunner 16 State SWD			
PROPOSALS.)			8. Well Number	#1		
1. Type of Well: Oil Well Gas Well Other						
2. Name of Operator			9. OGRID Number			
COG Operating, LLC 3. Address of Operator			229137 10. Pool name or Wildcat			
600 W. Illinois Ave, Midland, TX 79701			SWD; Bell Canyon-Cherry Canyon			
4. Well Location						
Unit Letter D : 330 feet from the N line and 330 feet from the W line						
Section 16 Township 26S				County Lea		
11. Elevation (Show						
3342' GR						
 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS CHANGE PLANS P AND A ALTERING CASING ALTERING CASING ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB P AND A COMMENCE DRILLING OPNS P AND A COMMENCE DRILLING OP SYSTEM OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 1. Set 7" CIBP @ 5500'. Circulate hole w/ MLF. Pressure test csg. Spot 25 sx cmt @ 5500-5400'. 2. Perf & Sqz 50 sx cmt @ 4500-4400'. 3. Spot 25 sx cmt @ 4500-4400'. 4. Spot 25 sx cmt @ 1087-987'. WOC & Tag. (1/Salt) 5. Perf & Sqz 50 sx cmt @ 1087-987'. WOC & Tag. (1/Salt) 5. Perf & Sqz 50 sx cmt @ 100'-Surface. 6. Perf & Sqz 50 sx cmt @ 100'-Surface. 7. Cut off well head, verify cmt to surface, weld on Dry Hole Marker. 4⁷ Aboure (-found 						
Spud Date:	ig Release Date	e:				
	1		11 11 0			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.						
SIGNATURE Abigail Anderson TITLE Agent DATE 12/14/2018 Type or print name Abigail Anderson E-mail address: ym@bcmandassociates.com PHONE: 432-580-7161						
For state Use Only						
APPROVED BY: <u>Xerry Forther</u> TITLE <u>Compliance</u> Officer <u>A</u> DATE 12-24-18 Conditions of Approval (if any):						

Conditions of Approval (if any):

30-025-40890 Gunner 16 State SWD 330' FNL, 330' FWL D-16-265-34e Leq, NM SWO-1367 6000 -6900' 1200 psi Max 17/2 1378"/54.5/J55/ JTC @ 855' 4005x"C"48 gel + 2505x "C" (circ 2219x) TOC 980'CBL 12/41 95/8"/40/J55, N80/BTC e 5282' 1300 5× HLC + 5005 x"C" (cire 2635x) 83/4" 6000' Delawan Sand 6900' 7"/26/J55/LTC e 7015' 325sx "C" Hudfield + 300sx Suppor C (Cive red dy & ahead of cant) 7015 32.0497322 M HOPS -103.4822998 35500



TD @ 7015'

GENERAL CONDITIONS OF APPROVAL:

- 1) Insure all bradenheads have been exposed, identified, and valves are operational prior to rigging up on well.
- 2) Contact the appropriate NMOCD District Office no later than 24 hours prior to moving in and rigging up.
- 3) A copy of the approved C103 intent to P&A should be distributed to the onsite company and plugging representatives. Approved procedures are good for a period of one year from approved date, unless otherwise specified on the C103 intent. Approvals past this date will require the submission and approval of a new C103 intent.
- 4) A company representative is required to be present to witness all operations including setting CIBP's, circulation of mud laden fluids, perforating, squeezing or spotting cement plugs, tags, or any other operations approved on the C103 intent to P&A. Company representative should contact the NMOCD and report all operations.
- 5) Any changes that may be required during plugging operations should be approved by the NMOCD before proceeding.
- 6) A closed loop system is to be used for all plugging operations. Contents of the steel pits to be hauled to a NMOCD permitted disposal facility.
- 7) Mud laden fluids must be placed between all cement plugs mixed at 25 sacks of salt gel per 100 barrels of brine.
- 8) All cement plugs will be 100' or 25 sacks cement, whichever is greater. Class 'C' cement will be used above 7500' and Class 'H' below 7500'.