Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

Lease Serial No. NMNM01747

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an

IAN 2 8 20

abandoned we	II. Use form 3160-3 (APD) for such	proposals.	1 2 0 2 U j	16. If Indian, Allottee	or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on page 2 RECEIVED If Unit or CA/Agreement, Name and/or No.							
1. Type of Well ☑ Oil Well ☐ Gas Well ☐ Other					8. Well Name and No. LEA UNIT 32H		
Name of Operator Contact: D. PATRICK DARDEN, PE LEGACY RESERVES OPERATING LPF Mail: pdarden@legacylp.com					9. API Well No. 30-025-42342		
			o. (include area code) 89-5200 Ext: 523			Exploratory Area	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			-	_	11. County or Parish, State		
Sec 12 T20S R34E SWSE 2FSL 1790FEL					LEA CO COUNTY, NM		
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA							
TYPE OF SUBMISSION	TYPE OF ACTION						
☑ Notice of Intent	☐ Acidize	☐ De	epen	☐ Production (Start/Resume)		■ Water Shut-Off	
	, Alter Casing		draulic Fracturing	. □ Reclama	ation	■ Well Integrity	
☐ Subsequent Report	☐ Casing Repair ☐ N		w Construction	■ Recomplete `		Other `	
☐ Final Abandonment Notice	☐ Change Plans	Plu	g and Abandon	☐ Tempor	arily Abandon		
	☐ Convert to Injection	D Plu	ug Back		Disposal		
determined that the site is ready for final inspection. Legacy Reserves request approval to recomplete the Lea Unit #32H in the Bone Spring Carbonate zones in the vertical section of the plugged back wellbore. Legacy's planned procedure for this work is as follows: - If needed drillout cmt to ~10,200'. - Perf, treat & test Bone Spring Carbonate zones fr/ ~9,900'-10,200'. - Return well to production on Beam Pumping Equipment in Bone Spring Carbonate zones.							
See attached well bore diagrams for current and proposed well bore conditions.							
Re-submitted per BLM's reguest. Initial FC#448845. See attached							
14. I hereby certify that the foregoing is true and correct. Electronic Submission #451434 verified by the BLM Well Information System For LEGACY RESERVES OPERATING LP, sent to the Hobbs							
Name (Printed/Typed) D. PATRICK DARDEN, PE			Title SR. ENGINEERING ADVISOR				
Signature (Electronic Submission)			Date 01/22/2019				
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
Approved By		Title		Date			
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Office				
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.							



Lea Unit #32H API # 30-025-42342

2' FSL & 1790' FEL, Section 12, T-20-S, R-34-E, Lea County, NM **CURRENT WELLBORE CONDITION** ft-RKB **Wellbore Sketch Surface Cement** - 20 bbl FW Spacer - Lead: 1345 sx of Class C, 13.50 ppg, 1.73 ft³/sx yield 1000' ---- Tail: 200 sx of Class C, 14.80 ppg, 1.33 ft³/sx yield - Circulated 97 sx/ 30 bbls of cement to surface 13-3/8" @ 1801' 54.5#, J-55, LTC 2000' ---3000' ---9-5/8" @ 4012' 4000' -40#, J-55, LTC **Intermediate Cement** 9-5/8" Stage tool @ 3819' - 40 bbl Gel spacer - 1st Stage Lead: 800 sx of P/C 35:65, 12.6 ppg, 2.05 ft³/sx yield 5000' ---- 1st Stage Tail: 300 sx of Class C, 14.8 ppg, 1.32 ft³/sx yield - 2nd Stage Lead: 800 sx of P/C 35:65, 12.6 ppg, 2.06 ft³/sx yield 9-5/8" @ 5400' - 2nd Stage Tail: 200 sx of Class C, 14.8 ppg, 1.33 ft³/sx yield 40#, HCL-80, LTC - Did not circulate cement to surface 6000' ----- Ran CBL on 20-Sep-2015: Estimated TOC @ 1736' - Pressure tested 9-5/8" annulus to 500 psi for 30 minutes on 04-Oct-2015 7000' ----**Production Cement** - 40 bbl FW Spacer w/ dye - Lead: 1600 sx of P/H 50:50, 11.90 ppg, 2.47 ft³/sx yield 8000' -- Tail: 1900 sx of PVL, 12.6 ppg, 1.33 ft³/sx yield Float Shoe = 2.00' - Circulated 795 sx / 350 bbls of cement to surface Shoe Joint = 44.46' - Floats did not hold, held pressure for 6 hours & WOC 9000' Float Collar = 2.25' **Wet Shoe Cement Displacement** Total Shoe Track = 48.71' Displaced cement w/ 10 bbls of sugar water & 35 bbls of 10% Cmt Plug fr/~10,017'-10,250' Top of Float @ ~18,332' Acetic Acid, and rupture plug float equipment Set down hard @ 10,252' KOP @ 10.339' 10,000' ---Marker Joint @ 16,086' 5-1/2" @ 18,381' EOC TVD: 10,932' TD TVD: 11,021' MD 11,000' 20#, HCP-110, GBCD 6854

7594'-



Lea Unit #32H API # 30-025-42342

TVD 2' FSL & 1790' FEL, Section 12, T-20-S, R-34-E, Lea County, NM PROPOSED WELLBORE CONDITION ft-RKB Wellbore Sketch Surface Cement - 20 bbl FW Spacer - Lead: 1345 sx of Class C, 13.50 ppg, 1.73 ft³/sx yield 1000' ---- Tail: 200 sx of Class C, 14.80 ppg, 1.33 ft³/sx yield - Circulated 97 sx/ 30 bbls of cement to surface 13-3/8" @ 1801' 54.5#, J-55, LTC 2000' — 3000' ---9-5/8" @ 4012' 4000' -**Intermediate Cement** 40#, J-55, LTC 9-5/8" Stage tool @ 3819' - 40 bbl Gel spacer - 1st Stage Lead: 800 sx of P/C 35:65, 12.6 ppg, 2.05 ft³/sx yield - 1st Stage Tail: 300 sx of Class C, 14.8 ppg, 1.32 ft³/sx yield 5000' — - 2nd Stage Lead: 800 sx of P/C 35:65, 12.6 ppg, 2.06 ft³/sx yield 9-5/8" @ 5400' - 2nd Stage Tail: 200 sx of Class C, 14.8 ppg, 1.33 ft³/sx yield 40#, HCL-80, LTC - Did not circulate cement to surface 6000' ---- Ran CBL on 20-Sep-2015: Estimated TOC @ 1736' - Pressure tested 9-5/8" annulus to 500 psi for 30 minutes on 04-Oct-2015 7000' ----**Production Cement** - 40 bbl FW Spacer w/ dye - Lead: 1600 sx of P/H 50:50, 11.90 ppg, 2.47 ft³/sx yield 8000' ---- Tail: 1900 sx of PVL, 12.6 ppg, 1.33 ft³/sx yield Float Shoe = 2.00' - Circulated 795 sx / 350 bbls of cement to surface **Proposed Bone Spring Carbonate Perfs** Shoe Joint = 44.46' - Floats did not hold, held pressure for 6 hours & WOC ~9,900'-10,200' Float Collar = 2.25' 9000' **Wet Shoe Cement Displacement** Total Shoe Track = 48.71' Displaced cement w/ 10 bbls of sugar water & 35 bbls of 10% Cmt Plug fr ~10,200'-10,250' Top of Float @ ~18.332' Acetic Acid, and rupture plug float equipment Set down hard @ 10,252' KOP @ 10,339' 10,000' ----Marker Joint @ 16,086' 5-1/2" @ 18,381' EOC TVD: 10,932' TD TVD: 11.021' MD 11,000' 20#, HCP-110, GBCD 6854' 7594'-

Laura Pina

From:

Laura Pina

Sent:

Tuesday, January 22, 2019 1:41 PM

To:

Pat Darden

Subject:

RE: EC Tran 448845 Rejected

Yes, I'm working on it. I received a handful of rejected sundry's including this one.

It's for the Lea Unit #32H NOI to Recomplete.

Thanks, Laura Piña NM Compliance Coordinator Legacy Reserves Operating LP 432.689.5273

----Original Message-----

From: Pat Darden

Sent: Tuesday, January 22, 2019 1:37 PM

To: Laura Pina

Subject: FW: EC Tran 448845 Rejected

Importance: High

Can you please take care of the request below.

Also, which well is this?

Thanks, Pat

----Original Message----

From: <u>PPERSZ@BEM.GOV</u> <u>| Incilio PPERSZ@BUM.GOV | Sant: Tuesday, Jeintany 22, 2019 N.05 PM-1</u>

To: Pat Darden

Subject lec ilian: 44,8845 Rejected