

Submit 1 Copy To Appropriate District Office

District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised July 18, 2013

WELL API NO. 30-025-31786
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: Vacuum Glorieta West Unit
8. Well Number: 30
9. OGRID Number: 4323
10. Pool name or Wildcat: Vacuum Glorieta

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other: INS

2. Name of Operator:
Chevron U.S.A. Inc.

3. Address of Operator:
6301 Deauville Blvd, Midland, TX. 79706

4. Well Location
Unit Letter J 2305 feet from the South line and 1391 feet from the East line
Section 25 Township 17-S Range 34-E NMPM County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
4,001' KB

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☒ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐
CLOSED-LOOP SYSTEM ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Chevron has determined the subject well is uneconomic to operate so the plan is to TA the well for future use per the following procedure:

1. MIRU, NDWH, NU BOPE.
2. POOH with all injection equipment.
3. Set CIBP @ ~5,950' MD and cap with 35' or 25 sxs of CMT. Circulate PKR fluid
4. Notify NMOCD to witness pressure test of casing and chart
5. File subsequent report with MIT chart to NMOCD

Chevron is requesting a 5-year TA status.

**Condition of Approval: notify
OCD Hobbs office 24 hours
prior of running MIT Test & Chart**

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jerry D. Poole TITLE Production Engineer DATE 6Feb2019

Type or print name Jerry D. Poole E-mail address: jerrypoole@chevron.com PHONE: (432) 687-7295

For State Use Only

APPROVED BY: [Signature] TITLE Compliance Supervisor DATE 2/8/2019

Conditions of Approval (if any):