Form 3160-5 (June 2015)

# **UNITED STATES**

FORM APPROVED

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT			Expir	es: January 31, 2018	
SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to re-enter any abandoned well. Use form 3160-3 (APD) for such proposals.				5:- Lease Serial No. NMNM01747 6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on page RECEIVED				7. If Unit or CA/Agreement, Name and/or No. 891006455A	
Type of Well     ☐ Gas Well    ☐ Other				8. Well Name and No. LEA UNIT 32H	
Name of Operator Contact: D. PATRICK DARDEN, PE LEGACY RESERVES OPERATING LÆ-Mail: pdarden@legacylp.com			9. API Well No. 30-025-423	9. API Well No. 30-025-42342-00-S1	
3a. Address 303 W WALL SUITE 1600 MIDLAND, TX 79702		3b. Phone No. (include area code) Ph: 432-689-5200	10. Field and Pool or Exploratory Area LEA-BONE SPRING		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			11. County or Parish, State		
Sec 12 T20S R34E SWSE 2FSL 1790FEL 32.344889 N Lat, 103.303775 W Lon			LEA COUN	TY, NM	
12. CHECK THE AF	PPROPRIATE BOX(ES)	TO INDICATE NATURE OF	F NOTICE, REPORT, OR	OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
Notice of Intent	☐ Acidize	□ Deepen	☐ Production (Start/Resume	e) Water Shut-Off	
	☐ Alter Casing	☐ Hydraulic Fracturing	☐ Reclamation ☐ Well Integrity		
☐ Subsequent Report	Casing Repair	■ New Construction	Recomplete	Other	
☐ Final Abandonment Notice	☐ Change Plans	□ Plug and Abandon	□ Temporarily Abandon		
	☐ Convert to Injection	☐ Plug Back	■ Water Disposal		
13. Describe Proposed or Completed Ope If the proposal is to deepen directions Attach the Bond under which the wor following completion of the involved testing has been completed. Final Ab determined that the site is ready for fi	illy or recomplete horizontally, k will be performed or provide operations. If the operation re- andonment Notices must be fil	give subsurface locations and measur the Bond No. on file with BLM/BIA sults in a multiple completion or reco	red and true vertical depths of all r Required subsequent reports mu mpletion in a new interval, a Form	pertinent markers and zones. st be filed within 30 days 13160-4 must be filed once	
Legacy Reserves request app in the vertical section of the plant as follows:					
<ul> <li>If needed drillout cmt to ~10,</li> <li>Perf, treat &amp; test Bone Spring</li> <li>Return well to production on</li> </ul>	Carbonate zones fr/ ~9,	900'-10,200'. nt in Bone Spring Carbonate z	rones.		
See attached well bore diagra	ms for current and propos	sed well bore conditions.			
	<del> </del>				

14. I hereby certify that the foregoing is true and correct Electronic Submission #451434 verified by the BLM Well Information System
For LEGACY RESERVES OPERATING LP, sent to the Hobbs
Committed to AFMSS for processing by PRISCILLA PEREZ on 01/29/2019 (19PP0855SE) D. PATRICK DARDEN, PE SR. ENGINEERING ADVISOR Name (Printed/Typed) Title Signature (Electronic Submission) 01/22/2019 THIS SPACE FOR FEDERAL OR STATE OFFICE USE FEB. 0 7 2019 Retroleum Engineer /s/ Jonathon Shepard Approved By Conditions of approval, if any, are attached. Approval of this notice does not warrent or certify that the applicant holds legal or equitable title to those rights in the subject which would entitle the applicant to conduct operations thereon. Carlsbad Field Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.


Office



### Lea Unit #32H API # 30-025-42342

2' FSL & 1790' FEL, Section 12, T-20-S, R-34-E, Lea County, NM


**CURRENT WELLBORE CONDITION** Float Shoe = 2.00' Shoe Joint = 44.46' Float Collar = 2.25' Total Shoe Track = 48.71 Top of Float @ ~18,332' 5-1/2" @ 18,381'





# **Lea Unit #32H**API # 30-025-42342

2' FSL & 1790' FEL, Section 12, T-20-S, R-34-E, Lea County, NM



#### **BUREAU OF LAND MANAGEMENT**

Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

### Conditions of Approval for Workover/Deepening of a Well

- 1. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any operations. For wells in Eddy County, call 575-361-2822. For wells in Lea County, call 575-393-3612
- 2. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,100 feet, a 3M system for a well not deeper than 13,600 feet, or a 5M system for a well not deeper than 22,700 feet (all depths are for measured well depth).
- 3. Cement: Notify BLM if cement fails to circulate.
- 4. <u>Subsequent Reporting:</u> Within 30 days after work is completed, file a Subsequent Report (Form 3160-5) to BLM. The report should give in detail the manner in which the work was carried out. <u>Show date work was completed</u>. If producing a new zone, submit a Completion Report (Form 3160-4) with the Subsequent Report.
- 5. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.
- 6. If well location is within the Timing Limitation Stipulation Area for Lesser Prairie-Chicken: From March 1<sup>st</sup> through June 15<sup>th</sup> annually, abandonment activities will be allowed except between the hours from 3:00 am and 9:00 am. Normal vehicle use on existing roads will not be restricted.