HOBBS OCD	
District I FEB 2 0 20 theregy State of New Mexico Minerals and Natural Resources Form C-I Revised August 1, 20 District II Bit S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 RECEIVED Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit one copy to appropri District Off District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 NFO Permit No. Cervision Use Or Cervision Use Or Application For Exception To NO-FLARE RULE 19.15.18.12 (See Rule 19.15.18.12 NMAC and Rule 19.15.7.37 NMAC)	iate fice
A. Applicant MATADOR PRODUCTION COMPANY	
whose address is 5400 LBJ FREEWAY, STE 1500, DALLAS, TX 75240,	
hereby requests an exception to Rule 19.15.18.12 for <u>90 days (beginning 03/02/19)</u> days or un	ntil
, Yr, for the following described tank battery (or LACT):	
Name of Lease Pickard TB Name of Pool Mescalero Escarpe; Bone Spring E-K;WOLFCAMP	
Location of Battery: Unit Letter <u>0</u> Section <u>20</u> Township <u>18S</u> Range <u>34E</u>	
Number of wells producing into battery (3) 30-025-41586; 30-025-41614; 30-025-4	2499
B. Based upon oil production of <u>410 (avg)</u> barrels per day, the estimated * volume	
of gas to be flared is <u>500</u> MCF; Value <u>per</u> day.	
C. Name and location of nearest gas gathering facility:	
DCP Midstream, LP line.	
D. DistanceEstimated cost of connection	
E. This exception is requested for the following reasons: Flaring due to freezing. equipment issues &	
high gas sales line issues.	
Pickard State 1H, 2H & Pickard State 124H	
OPERATOR Uber de contraction of the Oil Communitien	
I hereby certify that the rules and regulations of the Oil Conservation Division have been complied with and that the information given above is true and complete to the best of my knowledge and belief. Approved Until	_
Signature Ara Sta Gualdy	
By	
Printed Name Petroleum Engineer & Title Ava Monroe, Sr. Regulatory Analyst Title	******
E-mail Address_amonroe@matadorresources.com DateD2/22/17	
Date 2/20/14 Telephone No. 972-371-5218	

* Gas-Oil ratio test may be required to verify estimated gas volume.