70-029-42497

United States Department of the Interior



In Reply Refer to 3162.4 (P0220)

DALLAS, TX 75240

MATADOR PRODUCTION COMPANY

BUREAU OF LAND MANAGEMENT

Carisbad Field Office
620 E. Greene
Carlsbad, New Mexico 88220-6292 OBBS
www.nm.blm.gov

NAY

RECEIVED

March 29, 2019

5400 LBJ FREEWAY, SUITE 1500

Carlsbad Field Office OCD Hobbs

Gentlemen:

You're Application for Permit to Drill (APD) for the below referenced well has expired because drilling has not commenced per Onshore Order #1:

WELL NAME & NUMBER		ORIGINAL APD	EXTENSION
API	LOCATION	EXPIRATION	EXPIRATION
WIZARD 34 FEDERAL COM – 124H 3002542497	510'FSL & 150'FWL Sec.34-T16S-R32E	03/24/2017	03/23/2019

If a well has not been spud, but site construction activities have occurred please contact Jim Amos at (575) 234-5909 for surface reclamation instructions. If drilling operations have commenced on a well send all necessary reports (spud, casing/cementing, etc., 1 original and 3 copies) to the BLM so we may correct our records.

If you wish to drill this well at a later date, please submit a complete application (In AFMSS II data base) to this office. Since the original APD have expired, the resubmitted APD will be subject to all processing requirements including the current application fee and the 30-day posting period. Please note on the resubmitted APD that they were previously approved and we will review the expired file for information which will help expedite the processing.

If you have any questions, please contact Duncan Whitlock at (575) 234-5926.

Sincerely.

Cody Layton

Assistant Field Manager, Lands and Minerals

J. D. Whitlook of