UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Ob Hobbs

FORM APPROVED OMB NO. 1004-0137 31, 2018

Ехриса, лапиагу	
Lease Serial No.	
NIMNIMESTAD	

SUNDRY Do not use thi abandoned wel	6. 7.	NMNM56749 6. If Indian, Allottee or Tribe Name											
SUBMIT IN 1	7.	7. If Unit or CA/Agreement, Name and/or No.											
Type of Well		8. Well Name and No. FEDERAL USA L 08											
2. Name of Operator COG OPERATING LLC	Contact: E-Mail: dflores2@	ORES		9. API Well No. 30-025-32092-00-S1									
3a. Address ONE CONCHO CENTER 60 MIDLAND, TX 79701-4287	0 W ILLINOIS AVENUE	3b. Phone No Ph: 575-74		(include area code) 10. Field and Pool or Exploratory Area UNDESIGNATED									
4. Location of Well (Footage, Sec., T.	., R., M., or Survey Description		11. County or Parish, State										
Sec 14 T19S R33E SWSE 66		LEA COUNTY, NM											
12. CHECK THE AF	12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA												
TYPE OF SUBMISSION TYPE OF ACTION													
☐ Notice of Intent	☐ Acidize	Dee	pen	☐ Pro	duction	(Start/Resume)	7 🗖	Water S	Shut-Of	ff			
_	☐ Alter Casing	\\X \\ □ Hyd	Iraulic Fractu	iring 🔲 Rec	lamatio	n .		Nell In	tegrity				
Subsequent Report ■	☐ Casing Repair		v Constructio	on 🗖 Rec	Recomplete			Other					
☐ Final Abandonment Notice	☐ Change Plans	_ ,	g and Abando	_	-	orarily Abandon							
	☐ Convert to Injection ☐ Plug Back ☐ Water				ter Disp	er Disposal							
13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. 03/05/19 MIRU plugging equipment. POH w/ rods & pump. Dug out cellar, ND well head flange, NU BOP. RECLAMATION PROCEDURE POH w/ tbg. 03/06/19 RIH w/ tbg. tagged @ 3800'. Notified Patrick Mckelvey w/ BLM & POH w/ tbg. 03/06/19 RIH w/ tbg. tagged @ 3800'. Notified Patrick Mckelvey w/ BLM & POH w/ tbg. 03/07/19-03/11/19 RIH w/ drill bit, tagged @ 3800'. RU power swivel. Circ'd hole w/ H20. Drilled from 3800'. Tagged existing 5 1/2" CIBP @ 7115'. Circulated hole clean. POH w/tbg. 03/12/19 Spotted 35 sx class C cmt @ 5980-5626'. WOC. Tagged plug @ 56511'. 03/13/19 POH to -2500'. Shut down due to wind 03/14/19 Set 5 1/2" CIBP @ 3640'. Circulated hole w/ salt gel. Pressure tested csg, held 500 PSI. Spotted 85 sx class C cmt @ 3640'-2780' (Per Paul Flowers' request w/ BLM). WOC. Tagged plug @ 2770'. Perfd csg @ 1700'. Pressured up on perfs to 800 PSI. Spotted 35 sx class C cmt @ 60' & circulated to surface. Rigged down & moved off. 03/19/19 Moved in backhoe and welder, dug out cellar, cut off well head, and Patrick Mckelvey w/ BLM verified cellar, cut off deadmen,													
14. I hereby certify that the foregoing is true and correct. Electronic Submission #459501 verified by the BLM Well Information System For COG OPERATING LLC, sent to the Hobbs Committed to AFMSS for processing by PRISCILLA PEREZ on 03/28/2019 (19PP1470SE) Name (Printed/Typed) DELILAH FLORES Title REGULATORY TECHNICIAN													
Signature (Electronic S	Submission)		Date 03	/28/2019	ACC	CEPTED F	UK K		עאי				
	THIS SPACE F	OR FEDERA	L OR ST	ATE OFFICI	USE	APR 3	- 201	9					
Approved By			Title			prolinge		HAE					
Conditions of approval if any are attache	d. Approval of this notice doe	s not warrant or			B	UREAU OF LAN	D MANA	GENIE	141	1			

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)
*** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **

Office

CARLSBAD FIELD OFFICE

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Additional data for EC transaction #459501 that would not fit on the form

32. Additional remarks, continued

cleaned location, and moved off.

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its prediction approximation of the land and water to its predictive the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines (Comtact service companies, allowing plenty of time to have the risers and power lines and poles removed prior to reclamation, don't wait till the last day and try to get them to remove infrastructure). Strip and remove caliche, contour the location to blend with the surrounding landscape, re-distribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up from in the APD process as per Onshore Oil and Gas Order No. 1
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would
- be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Nonce of Intent or the Subsequent Report of Abandonment Sundry Notices and Reports on Wells (Form 3160-5), is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well completion, and final reclamation
- 3 The operator must file a Subsequent Report Plug and Abandonnent (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you

- and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909, 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Crystal Weaver
Environmental Protection Specialist
575-234-5943

Shelly Tucker
Environmental Protection Specialist
575-234-5979

Trishia Bad Bear, Hobbs Field Station Natural Resource Specialist 575-393-3612