

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

HOBBS OCD

FORM APPROVED
OMB No. 1004-0137
Expires: January 31, 2018

JUN 10 2019

SUNDRY NOTICES AND REPORTS ON WELLS
*Do not use this form for proposals to drill or to re-
abandoned well. Use Form 3160-3 (APD) for such proposals.*

RECEIVED

SUBMIT IN TRIPLICATE - Other instructions on page 2

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator Fulfer Oil & Cattle LLC

3a. Address P.O. box 1227
Jal NM. 882523b. Phone No. (include area code)
575-395-99704. Location of Well (Footage, Sec., T., R., M., or Survey Description)
UL I, SEC 26, T25S, R37E

5. Lease Serial No. NMLC 032579E

6. If Indian, Allottee or Tribe Name

7. If Unit of CA/Agreement, Name and/or No.

8. Well Name and No. Carlson B26 #4

9. API Well No. 30-025-11796

10. Field and Pool or Exploratory Area
Langlie Mattix, 7RVS, Queen, GB

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☒ Notice of Intent☐ Subsequent Report☐ Final Abandonment Notice☐ Acidize☐ Alter Casing☐ Casing Repair☐ Change Plans☐ Convert to Injection☐ Deepen☐ Hydraulic Fracturing☐ New Construction☐ Plug and Abandon☐ Plug Back☐ Production (Start/Resume)☐ Reclamation☐ Recomplete☒ Temporarily Abandon☐ Water Disposal☐ Water Shut-Off☐ Well Integrity☐ Other

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

We request to Temporarily Abandon this well by placing a CIBP within 100' of existing perforations at 2980-3048 and placing 35' dump bail of cement on top of the CIBP. we will perform procedure after we pull the well and test casings. our request for TA Status is so we can evaluate the well for possible fracture in Jal mat Gas Zones or other potential zones. we will call for inspector to come and witness chart to complete TA status. then send in subsequent report.

SEE ATTACHED FOR
CONDITIONS OF APPROVALAPPROVED FOR 12 MONTH PERIOD
ENDING 5/1/2020

OFFICIAL HOBBS

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)

Mike Dennis

Production Superintendent

Title

Signature

Mike Dennis

Date

5/1/19

THE SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

/s/Zota Stevens

PETROLEUM ENGINEER

Title

Date

5/1/2019

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

CFO

Title 18 U.S.C Section 1001 and Title 43 U.S.C Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

XZ NMOC D 6-12-19

FOR RECORD ONLY

**BUREAU OF LAND MANAGEMENT
Carlsbad Field Office
620 East Greene Street
Carlsbad, New Mexico 88220
575-234-5972**

**Temporary Abandonment of Wells on Federal Lands
Conditions of Approval**

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
2. A description of the temporary abandonment procedure.
 - a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging. CIBP must be capped with minimum 25 sacks cement, **placed with tubing**.

[REDACTED] The casing integrity test (CIT) is required for all wells in which oil or gas is encountered in paying quantities. The casing integrity test (CIT) is required for all wells in which oil or gas is encountered in paying quantities.

c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.

d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.

[REDACTED] The scheduled Casing Integrity Test. For [REDACTED]

3. [REDACTED] 43 CFR 3162.3-4 (a) The operator shall promptly plug and abandon...wells in which oil or gas is not encountered in paying quantities...

Wells that successfully pass the casing integrity test may be approved for Temporary Abandonment (TA) status provided that the operator:

1. [REDACTED] TA approval with a 30-day time frame.
2. Describes the temporary abandonment procedure.
3. Attaches a clear copy or the original of the pressure test chart.
4. [REDACTED] The use of well with time frame that [REDACTED]

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

1. A procedure to repair the casing so that a TA approval can be granted.
2. A procedure to plug and abandon the well.

Carlson B-26 #4

Well Name: Meyers B #2 Submit Subsequent Report and well bore diagram with all Perforations and CIBP with tops of cement. Well may be approved to be TA for a period of 12 months or until 6/1/2010 after successful MIT and subsequent report is submitted. This well has been shut-in since March 2011.

