Submit 1 Copy To Appropriate District Office <u>District 1</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	State of New Me Energy, Minerals and Natu OIL CONSERVATION 1220 South St. Fran Santa Fe, NM 87	nal Resources DIVISION acis Dr.	WELL API NO. 30-025-30147 5. Indicate Type	FEE _
SUNDRY NOTI (DO NOT USE THIS FORM FOR PROPOSITION OF THE SERVOIR. USE "APPLICATION OF THE SERVOIR. USE "APPLICATION OF THE SERVOIR OF THE SER	Gas Well Other	OCD	 7. Lease Name of State 2 8. Well Number 9. OGRID Number 142072 10. Pool name of "Shipp" Strawn 	ber r Wildcat
4. Well Location Unit Letter_530 Section 2	er, CO 80202 :feet from theNorth Township 17S 11. Elevation (Show whether DR) RKB = 3,768'	line and660 Range 37E , RKB, RT, GR, etc.)	NMPM	m theEastline County Lea
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: Recomplete in the Paddo 13. Describe proposed or comp	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Ck Fm. Cleted operations. (Clearly state all ork). SEE RULE 19.15.7.14 NMAG	SUB: REMEDIAL WORI COMMENCE DRI CASING/CEMENT OTHER: pertinent details, and	SEQUENT RE K LLING OPNS. T JOB d give pertinent da	EPORT OF: ALTERING CASING P AND A tes, including estimated date
KPK is proposing to recomplete the preserve the lease. An attempt was trunsuccessful due to encountering strusuccessful d	well in the Paddock formation (see made to restore production from the ack tubing and possible collapsed col- letion the wellbore must be plugged emaining tubing in the wellbore from bmitted for the plugback procedure, attempt to place cement from this de- ermediate string will dictate whether	originally complete asing. d back to approx 6, om a failed fishing at a succeepth to 4,000°. The aer the cement can be	ed "Shipp Strawn" 1900' to cover and ttempt to recover the ssful plugback operability to establish placed via circula	seal-off an area of suspected he stuck 2 7/8" tubing. (A cration, squeeze perforations circulation between the 5 ½" tion or a more traditional

Assuming the plugback operation and placing cement sufficiently above and below the Paddock formation is successful, the following intervals will be perforated with a 4" casing gun at 2 SPF: 6,742' – 58'; 6,776' – 88'; 6,798' – 6,810'. The gross perforated interval will be acidized with 4,000 gal. 15% NeFe + 80 ball sealers, flowed back and placed on pump to determine producing rates.

KPK expects to commence recompletion operations the week of

. 2019

JULY 16, por

Spud Date:		Rig Release Date:				
I hereby certif	ry that the information above is true an	nd complete to the best o	f my knowledge and belief.			
SIGNATURE	Mr C. Namin	TITLE <i>V.P.</i>	EXPL. & PROD.	DATE 9-10-2019		
Type or print name ALAN C. WARRISON E-mail address: AHARRISON KPK. COM PHONE: 825-4822 For State Use Only						
APPROVED Conditions of	BY: Approval (Hany):	TITLEPetro	leum Engineer	DATE 07/12/19		

.

KP Kauffmamn Company, Inc State #2-1 API No. 30-025-30147 NE/NE Sec. 2-17S-37E Lea Co., NM

"Wellbore Diagram - Proposed Recompletion"

KB: 3,768' GL: 3,751'

