United States Department of the Interior 42574



BUREAU OF LAND MANAGEMENT HOBBS OCD

Carlsbad, New Mexico 88220-6292 NOV 21 2019

In Reply Refer to 3162.4 (P0220)

Cimarex Energy Co 202 S. Cheyenne Ave, Suite 1000 Tulsa, OK 74103

Deriston Movember 15, 2019 ACD Palling

## Gentlemen:

You're Application for Permit to Drill (APD) for the below referenced well has expired because drilling has not commenced per Onshore Order #1:

WELL NAME & NUMBER		ORIGINAL APD	<b>EXTENSION</b>
API#	LOCATION	EXPIRATION	<b>EXPIRATION</b>
EAST LUSK 15 FEDERAL COM – 4H	900'FNL & 330'FEL	05/14/2017	05/13/2019
3002542574	Sec.15-T19S-R32E		

If a well has not been spud, but site construction activities have occurred please contact Jim Amos at (575) 234-5909 for surface reclamation instructions. If drilling operations have commenced on a well send all necessary reports (spud, casing/cementing, etc., 1 original and 3 copies) to the BLM so we may correct our records.

If you wish to drill this well at a later date, please submit a complete application (In AFMSS II data base) to this office. Since the original APD have expired, the resubmitted APD will be subject to all processing requirements including the current application fee and the 30-day posting period. Please note on the resubmitted APD that they were previously approved and we will review the expired file for information which will help expedite the processing.

If you have any questions, please contact Chris Walls at (575) 234-2234.

Cody Layton

Sincerely

Assistant Field Manager, Lands and Minerals