HOBBS OCD

State of New Mexico Minerals and Employed Submit One Copy To Appropriate District Form C-103 Office Energy, Minerals and Natura Revised November 3, 2011 District I WELL API NO. 1625 N. French Dr., Hobbs, NM 88240 OIL CONSERVARE District II 30-025-31284 811 S. First St., Artesia, NM 88210 5. Indicate Type of Lease 1220 South St. Francis Dr. District III STATE ☐ FEE ☒ 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 District IV 6. State Oil & Gas Lease No. 1220 S. St. Francis Dr., Santa Fe, NM SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A LOVINGTON PADDOCK UNIT DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH 8. Well Number PROPOSALS.) 104 1. Type of Well: ☐ Oil Well ☐ Gas Well ☒ Other WATER INJECTION 9. OGRID Number 2. Name of Operator CHEVRON MIDCONTINENT L.P. 3. Address of Operator 10. Pool name or Wildcat 6301 Deauville Blvd., Midland, TX 79706 LOVINGTON: PADDOCK 4. Well Location: Unit Letter D: 75 feet from the NORTH line and 240 feet from the WEST line Township 16-S Range 37-E NMPM County LEA 11. Elevation (Show whether DR. RKB, RT. GR. etc.) 3,831' GL 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK □ PLUG AND ABANDON □ REMEDIAL WORK ALTERING CASING □ **CHANGE PLANS** COMMENCE DRILLING OPNS.□ **TEMPORARILY ABANDON** P AND A **PULL OR ALTER CASING** MULTIPLE COMPL **CASING/CEMENT JOB** OTHER: □ Location is ready for OCD inspection after P&A All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.) All other environmental concerns have been addressed as per OCD rules. Mark Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from nonretrieved flow lines and pipelines. [X] If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well location, except for utility's distribution infrastructure. When all work has been completed, return this form to the appropriate District office to schedule an inspection. Katherine TITLE Decommissioning Project Manager DATE 12.18.19 TYPE OR PRINT NAME \_\_Katherine Papageorge\_E-MAIL: \_Katherine.Papageorge@chevron.com\_\_ PHONE: \_\_\_832-854-5291\_\_ For State Use Only A DATE 12.20-19 TITLE