Submit 1 Copy To Appropriate District Office	State of New Mexico	Form C-103
District I	Energy, Minerals and Natural Resour	ces October 13, 2009
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION	ON 30-025-04055
District III	1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505	STATE STEE
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	Santa 1.C, 14101 67505	6. State Oil & Gas Lease No.
87505		
SUNDRY NOTI	CES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
	SALS TO DRILL OR TO DEEPEN OR PLUG BACK TO)A
PROPOSALS.)	CATION FOR PERMIT" (FORM C-101) FOR SUCH	State T
	Gas Well 🛛 HOBBS OC	8. Well Number 3
2. Name of Operator	HOBBS OF	9. OGRID Number 873
Apache Corp.		7. Odiab Namoci 073
3. Address of Operator	JUN 0 9 2020	10. Pool name or Wildcat
P O box Drawer D Monument NM	88265	Eumont Yates 7 Rivers Queen
		B
4. Well Location Unit Letter F : 1980 feet from the RECEIVED; Section 26 Page 26 Pag		
Unit LetterF:	1980feet from theN line	
Section 25	Township 195 Range	
	11. Elevation (Show whether DR, RKB, RT,	GR, etc.)
12. Check A	appropriate Box to Indicate Nature of I	Notice, Report or Other Data
		•
NOTICE OF IN		SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIA	AL WORK ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS COMME	NCE DRILLING OPNS.□ P AND A □
PULL OR ALTER CASING	MULTIPLE COMPL CASING/	CEMENT JOB
DOWNHOLE COMMINGLE		
OTHER:	☐ OTHER:	TA Test Extension
13. Describe proposed or comp	eted operations. (Clearly state all pertinent de	tails, and give pertinent dates, including estimated date
13. Describe proposed or composed wo	eted operations. (Clearly state all pertinent dork). SEE RULE 19.15.7.14 NMAC. For Mul	
13. Describe proposed or comp	eted operations. (Clearly state all pertinent dork). SEE RULE 19.15.7.14 NMAC. For Mul	tails, and give pertinent dates, including estimated date
13. Describe proposed or composed wo	eted operations. (Clearly state all pertinent dork). SEE RULE 19.15.7.14 NMAC. For Mul	tails, and give pertinent dates, including estimated date
 Describe proposed or composed of starting any proposed we proposed completion or recomposed. 	eted operations. (Clearly state all pertinent de rk). SEE RULE 19.15.7.14 NMAC. For Mul completion.	tails, and give pertinent dates, including estimated date
Describe proposed or composed of starting any proposed we proposed completion or recutation. RU Sunrise Truck and characteristics.	eted operations. (Clearly state all pertinent de rk). SEE RULE 19.15.7.14 NMAC. For Mul ompletion.	tails, and give pertinent dates, including estimated date
Describe proposed or composed for starting any proposed we proposed completion or reconstruction. RU Sunrise Truck and characteristics. Open surface casing and me	eted operations. (Clearly state all pertinent de rk). SEE RULE 19.15.7.14 NMAC. For Mul ompletion. recorder. onitor during test.	stails, and give pertinent dates, including estimated date tiple Completions: Attach wellbore diagram of
 Describe proposed or composed starting any proposed we proposed completion or rec RU Sunrise Truck and char Open surface casing and me Test casing to 562# for 32 r 	eted operations. (Clearly state all pertinent de rk). SEE RULE 19.15.7.14 NMAC. For Mul ompletion.	stails, and give pertinent dates, including estimated date tiple Completions: Attach wellbore diagram of
 Describe proposed or composed starting any proposed we proposed completion or reconstruction. RU Sunrise Truck and chart Open surface casing and median Test casing to 562# for 32 results. Release pressure. RDMO. 	eted operations. (Clearly state all pertinent de rk). SEE RULE 19.15.7.14 NMAC. For Mul ompletion. t recorder. onitor during test. ninutes, ending pressure 558#. Record test on	stails, and give pertinent dates, including estimated date tiple Completions: Attach wellbore diagram of
 Describe proposed or composed starting any proposed we proposed completion or reconstruction. RU Sunrise Truck and chart Open surface casing and median Test casing to 562# for 32 results. Release pressure. RDMO. 	eted operations. (Clearly state all pertinent de rk). SEE RULE 19.15.7.14 NMAC. For Mul ompletion. recorder. onitor during test.	stails, and give pertinent dates, including estimated date tiple Completions: Attach wellbore diagram of
 Describe proposed or composed starting any proposed we proposed completion or reconstruction. RU Sunrise Truck and chart Open surface casing and median Test casing to 562# for 32 results. Release pressure. RDMO. 	eted operations. (Clearly state all pertinent de rk). SEE RULE 19.15.7.14 NMAC. For Mul ompletion. t recorder. onitor during test. ninutes, ending pressure 558#. Record test on	stails, and give pertinent dates, including estimated date tiple Completions: Attach wellbore diagram of
 Describe proposed or composed starting any proposed we proposed completion or reconstruction. RU Sunrise Truck and chart Open surface casing and median Test casing to 562# for 32 results. Release pressure. RDMO. 	eted operations. (Clearly state all pertinent derk). SEE RULE 19.15.7.14 NMAC. For Multiple operation. Trecorder. onitor during test. onitors, ending pressure 558#. Record test on tenhead test. Request TA extension.	stails, and give pertinent dates, including estimated date tiple Completions: Attach wellbore diagram of chart.
 Describe proposed or composed starting any proposed we proposed completion or reconstruction. RU Sunrise Truck and chart Open surface casing and median Test casing to 562# for 32 results. Release pressure. RDMO. 	eted operations. (Clearly state all pertinent derk). SEE RULE 19.15.7.14 NMAC. For Multiple operation. Trecorder. Spring test. Spring test. Spring test. Spring test on tenhead test. Request TA extension. FINAL TA	stails, and give pertinent dates, including estimated date tiple Completions: Attach wellbore diagram of chart.
 Describe proposed or composed starting any proposed we proposed completion or reconstruction. RU Sunrise Truck and chart Open surface casing and median Test casing to 562# for 32 results. Release pressure. RDMO. 	eted operations. (Clearly state all pertinent derk). SEE RULE 19.15.7.14 NMAC. For Multiple operation. Trecorder. Spring test. Spring test. Spring test. Spring test on tenhead test. Request TA extension. FINAL TA	stails, and give pertinent dates, including estimated date tiple Completions: Attach wellbore diagram of chart.
 Describe proposed or composed starting any proposed we proposed completion or reconstruction. RU Sunrise Truck and chart Open surface casing and median Test casing to 562# for 32 results. Release pressure. RDMO. 	eted operations. (Clearly state all pertinent de rk). SEE RULE 19.15.7.14 NMAC. For Multiple ompletion. Trecorder. In recorder. In recorder	stails, and give pertinent dates, including estimated date tiple Completions: Attach wellbore diagram of chart. STATUS- EXTENSION IRES: 1 2 4
 Describe proposed or composed starting any proposed we proposed completion or reconstruction. RU Sunrise Truck and characteristics. Open surface casing and mediate to 562# for 32 rest casing to 562# for 32 rest. Release pressure. RDMO. See attached chart and Braden. 	eted operations. (Clearly state all pertinent de rk). SEE RULE 19.15.7.14 NMAC. For Multiple ompletion. Trecorder. onitor during test. onitor during test. onitores, ending pressure 558#. Record test on tenhead test. Request TA extension. FINAL TA Approval of TA EXP Well needs to be Pt.	stails, and give pertinent dates, including estimated date tiple Completions: Attach wellbore diagram of chart.
 Describe proposed or composed starting any proposed we proposed completion or reconstruction. RU Sunrise Truck and chart Open surface casing and median Test casing to 562# for 32 results. Release pressure. RDMO. 	eted operations. (Clearly state all pertinent de rk). SEE RULE 19.15.7.14 NMAC. For Multiple ompletion. Trecorder. Specific of the recorder o	STATUS- EXTENSION IRES:
 Describe proposed or composed starting any proposed we proposed completion or reconstruction. RU Sunrise Truck and characteristics. Open surface casing and mediate to 562# for 32 rest casing to 562# for 32 rest. Release pressure. RDMO. See attached chart and Braden. 	eted operations. (Clearly state all pertinent de rk). SEE RULE 19.15.7.14 NMAC. For Multiple ompletion. Trecorder. Specific of the recorder o	STATUS- EXTENSION IRES:
13. Describe proposed or composed starting any proposed we proposed completion or reconstruction. 1. RU Sunrise Truck and chart 2. Open surface casing and me 3. Test casing to 562# for 32 r 4. Release pressure. RDMO. 5. See attached chart and Brade Spud Date:	recorder. onitor during test. oninutes, ending pressure 558#. Record test on tenhead test. Request TA extension. FINAL TA Approval of TA EXP Well needs to be Pt to PRODUCTION BY THE DATE STA	STATUS- EXTENSION IRES:
13. Describe proposed or composed starting any proposed we proposed completion or reconstruction. 1. RU Sunrise Truck and chart 2. Open surface casing and me 3. Test casing to 562# for 32 r 4. Release pressure. RDMO. 5. See attached chart and Brade Spud Date:	eted operations. (Clearly state all pertinent de rk). SEE RULE 19.15.7.14 NMAC. For Multiple ompletion. Trecorder. Specific of the recorder o	STATUS- EXTENSION IRES:
13. Describe proposed or composed starting any proposed we proposed completion or reconstruction. 1. RU Sunrise Truck and chart 2. Open surface casing and me 3. Test casing to 562# for 32 r 4. Release pressure. RDMO. 5. See attached chart and Brade Spud Date:	recorder. onitor during test. oninutes, ending pressure 558#. Record test on tenhead test. Request TA extension. FINAL TA Approval of TA EXP Well needs to be Pt to PRODUCTION BY THE DATE STA	STATUS- EXTENSION IRES:
13. Describe proposed or composed starting any proposed we proposed completion or recomposed com	rk). SEE RULE 19.15.7.14 NMAC. For Multiple of the properties of t	STATUS- EXTENSION IRES:
13. Describe proposed or composed starting any proposed we proposed completion or reconstruction. 1. RU Sunrise Truck and chart 2. Open surface casing and me 3. Test casing to 562# for 32 r 4. Release pressure. RDMO. 5. See attached chart and Brade Spud Date:	recorder. onitor during test. oninutes, ending pressure 558#. Record test on tenhead test. Request TA extension. FINAL TA Approval of TA EXP Well needs to be Pt to PRODUCTION BY THE DATE STA	STATUS- EXTENSION IRES:
13. Describe proposed or composed starting any proposed we proposed completion or recomposed completion or recompletion or recomposed completion or recomposed completion or recomposed completion or recompletion or recomp	eted operations. (Clearly state all pertinent de rk). SEE RULE 19.15.7.14 NMAC. For Multiple ompletion. Trecorder. Initiation during test. Init	STATUS- EXTENSION Chart. STATUS- EXTENSION IRES:
13. Describe proposed or composed starting any proposed we proposed completion or recomposed completion or recompletion or recomposed completion or recompletion or recomposed completion or recompl	eted operations. (Clearly state all pertinent de rk). SEE RULE 19.15.7.14 NMAC. For Multiple ompletion. Trecorder. Initiation during test. Init	STATUS- EXTENSION IRES:
13. Describe proposed or composed starting any proposed we proposed completion or recomposed completion or recompletion or recomposed completion or recomposed completion or recomposed completion or recompletion or recomp	eted operations. (Clearly state all pertinent de rk). SEE RULE 19.15.7.14 NMAC. For Multiple ompletion. Trecorder. Initiation during test. Init	STATUS- EXTENSION Chart. STATUS- EXTENSION IRES:
13. Describe proposed or composed starting any proposed we proposed completion or recomposed completion or recompletion or recomposed completion or recompletion or recomposed completion or recompl	leted operations. (Clearly state all pertinent de rk). SEE RULE 19.15.7.14 NMAC. For Multiple ompletion. It recorder. It	STATUS- EXTENSION Chart. STATUS- EXTENSION IRES:/ 2_/ .UGGED OR RETURNED TED ABOVE:
13. Describe proposed or composed starting any proposed we proposed completion or recomposed completion or recompletion or recomposed completion or recompletion or recomposed completion or recompl	eted operations. (Clearly state all pertinent de rk). SEE RULE 19.15.7.14 NMAC. For Multiple ompletion. Trecorder. Initiation during test. Init	STATUS- EXTENSION Chart. STATUS- EXTENSION IRES:

RECEIV 33 45 9; RECEIVED HOBBS OCD 0202 6 0 NOS # 1 378-561-52-1 54040-5-0-08 = 10