

Form 9-331  
(May 1963)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE  
(Other instructions  
verse side)

Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.  
**LC 100331 C**  
**S. Caprock (Moon Unit)**

6. IF INDIAN, ALLOTTEE OR TRIBE NAME  
**Chaves County, N.M.**

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

7. UNIT AGREEMENT NAME  
**S. Caprock (Moon Unit)**

8. FARM OR LEASE NAME  
**S. Caprock (Moon Unit)**

9. WELL NO.  
**13 - Tr. 11**

10. FIELD AND POOL, OR WILDCAT  
**S. Caprock (Moon Unit)**

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
**Sec. 5**

12. COUNTY OR PARISH  
**Chaves**

13. STATE  
**New Mexico**

1. OIL WELL  GAS WELL  OTHER

2. NAME OF OPERATOR  
**Union Oil of California**

3. ADDRESS OF OPERATOR  
**300 N. Maricofield - Midland, Texas**

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface  
**660 NW, 660' P.M., Sec. 5, Twp. 15 S, Rng. 31 E**

14. PERMIT NO.  
**GL 4439**

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF   
FRACTURE TREAT   
SHOOT OR ACIDIZE   
REPAIR WELL   
(Other)

PULL OR ALTER CASING   
MULTIPLE COMPLETE   
ABANDON\*   
CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF   
FRACTURE TREATMENT   
SHOOTING OR ACIDIZING   
(Other)

REPAIRING WELL   
ALTERING CASING   
ABANDONMENT\*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

**Plugging Procedures Below**

- 1. 10 3/4" @ 325' W/225 Sz.**
- 2. 9 1/2" @ 3146' W/625 Sz.**
- 3. Perf. @ 3146' - 3115'**

**Plug #1 25 Sz. @ 3100'**  
**Plug #2 5 Sz. @ Surface**

**Recovered 1000' Tubing**

**Establish Dry Hole Marker**

RECEIVED  
AUG 11 1971  
GEOLOGICAL SURVEY  
MIDLAND, TEXAS

**H. D. Oden, Inc.**

18. I hereby certify that the foregoing is true and correct

**Agent for Union Oil  
of California**

SIGNED \_\_\_\_\_

TITLE \_\_\_\_\_

DATE **August 11, 1971**

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

TITLE \_\_\_\_\_

DATE \_\_\_\_\_

APPROVED  
AUG 29 1971  
K. L. BEEKMAN  
ACTING DISTRICT ENGINEER

\*See Instructions on Reverse Side

## Instructions

**General:** This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

**Item 4:** If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

**Item 17:** Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.