

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. LC 068900
7. Unit Agreement Name S. Caprock Queen Unit
8. Farm or Lease Name S. Caprock Queen Unit
9. Well No. T-39, W-8, Sec. 30
10. Field and Pool, or Wildcat S. Caprock Queen Unit
12. County Curves

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Union Oil of California
3. Address of Operator 500 N. Maricopa - Midland, Texas
4. Location of Well UNIT LETTER H , 1650 FEET FROM THE N LINE AND 950 FEET FROM THE E LINE, SECTION 30 TOWNSHIP 15 S RANGE 31 E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) OL 4435

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/> CHANGE PLANS <input type="checkbox"/> OTHER <input type="checkbox"/>
REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/> OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugging Procedures Below:

1. 8 5/8" @ 308'
2. 5 1/2" @ 3153' w/400 in.
3. Perf. @ 3140' - 3192'

Plug #1 - 100' Plug @ Perf.
 Plug #2 - 100' Plug @ Stub of 5 1/2"
 Plug #3 - 100' Plug in and out of Surface
 Plug #4 - 20' Plug @ Surface

Establish Dry Hole Marker

H. D. Oden, Inc.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED H. D. Oden	TITLE Agent for Union Oil of California	DATE June 30, 1971
APPROVED BY [Signature]	TITLE SUPERVISOR DISTRICT I	DATE JUL 7 1971
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

JUL 6 1971

OIL CONSERVATION COMM.
HOBBS, N. M.