

|                        |  |
|------------------------|--|
| NO. OF COPIES RECEIVED |  |
| DISTRIBUTION           |  |
| SANTA FE               |  |
| FILE                   |  |
| U.S.G.S.               |  |
| LAND OFFICE            |  |
| OPERATOR               |  |

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

|  |
|--|
| 5a. Indicate Type of Lease<br>State <input checked="" type="checkbox"/> Fee <input type="checkbox"/> |
| 5. State Oil & Gas Lease No.   |
| 7. Unit Agreement Name No. 1<br>No. Caprock Queen Unit   |
| 8. Farm or Lease Name No. 1<br>No. Caprock Queen Unit  |
| 9. Well No.<br>Tract 8, Well No. 8   |
| 10. Field and Pool, or Wellcat<br>Caprock Queen (Chaves)   |
| 11. Elevation (Show whether DF, RT, GR, etc.)<br>4394' G.L.  |
| 12. County<br>Chaves   |

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL  GAS WELL  OTHER- Injection Well

2. Name of Operator  
Thunderbird Oil Corporation

3. Address of Operator  
P. O. Box 1778, Midland, Texas 79701

4. Location of Well  
UNIT LETTER H 1650 FEET FROM THE North LINE AND 330 FEET FROM  
THE East LINE, SECTION 36 TOWNSHIP 12-S RANGE 31-E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)  
4394' G.L.

12. County  
Chaves

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

|  |  |   |   |
|--|--|---|---|
| NOTICE OF INTENTION TO:                        |  | SUBSEQUENT REPORT OF:                               |   |
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input checked="" type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/>              | ALTERING CASING <input type="checkbox"/>      |
| TEMPORARILY ABANDON <input type="checkbox"/>   | CHANGE PLANS <input type="checkbox"/>                | COMMENCE DRILLING OPNS. <input type="checkbox"/>    | PLUG AND ABANDONMENT <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/>  | OTHER <input type="checkbox"/>                       | CASING TEST AND CEMENT JOB <input type="checkbox"/> | OTHER <input type="checkbox"/>                |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-5/8" @ 251' w/239 sx.  
5-1/2" @ 3004' w/100 sx.  
212' of 3-1/2" Liner @ 2810-3022'

1. Displace hole with salt base mud.
2. Set CIBP @ 2700'.
3. Set 35' cement plug (5 sx.) on top of CIBP.
4. Cut off & pull 5-1/2" casing @ approximately 800'.
5. Spot 25 sx. cement plug in-and-out of 5-1/2" casing stub.
6. Spot 35 sx. cement plug in-and-out of 8-5/8" surface casing @ 194-308'.
7. Spot 10 sx. cement plug @ surface and erect 4-1/2" regulation dry hole marker.
8. Clean up location for N.M.O.C.C. inspection and approval.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Harry F. Schuman TITLE President DATE 11-29-74

APPROVED BY Joe [Signature] TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY: \_\_\_\_\_

**RECEIVED**

**DEC 4 1974**

**OIL CONSERVATION COMM.  
HOBBS, N. M.**