

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPlicate
(Other instructions on
verse side)

LC 068370

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE OR WELL SERIAL NO.

6. OPERATOR NAME UNIT

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Concho County New Mexico

7. UNIT AGREEMENT NAME

S. Concho Basin Unit

8. FARM OR LEASE NAME

S. Concho Basin Unit

9. WELL NO.

15 - Tr. 7 A

10. FIELD AND POOL, OR WILDCAT

S. Concho Basin Unit

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 33

12. COUNTY OR PARISH

Concho

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL GAS WELL OTHER

2. NAME OF OPERATOR
Union Oil of California

3. ADDRESS OF OPERATOR
900 N. Harrison St. - Midland, Texas

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
990' FSL, 1900' DVL, Sec. 33, Township 14 S, Range 31 E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

GL 1442

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
(Other)

PULL OR ALTER CASING
MULTIPLE COMPLETE
ABANDON*
CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF
FRACTURE TREATMENT
SHOOTING OR ACIDIZING
(Other)

REPAIRING WELL
ALTERING CASING
ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Plugging Procedures Below:

1. 8 5/8" @ 330'
2. 5 1/2" @ 3128' w/100 Sz.
3. Surf. @ 3110' - 3116'

Plug #1 - 100' Plug @ Surf.
Plug #2 @ 100' Plug @ 5 1/2" Stub
Plug #3 - 100' Plug in and out of surface
Plug #4 - 20' Plug @ Surface

Establish Dry Hole Marker

RECEIVED

JUL 8 1971

RECEIVED
JUL 6 1971
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

H. B. Olsen, Inc.

O. C. C.
ARTESIA, OFFICE

18. I hereby certify that the foregoing is true and correct

SIGNED

H. B. Olsen

TITLE

**Agent for Union Oil
of California**

DATE

June 30, 1971

(This space for Federal or State office use)

TITLE

DATE

APPROVED
JUL - 7 1971
R. L. Beekman
R. L. BEEKMAN
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

COPIES