

NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

MISCELLANEOUS NOTICES

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Notice by Checking Below

NOTICE OF INTENTION TO CHANGE PLANS		NOTICE OF INTENTION TO TEMPORARILY ABANDON WELL		NOTICE OF INTENTION TO DRILL DEEPER	
NOTICE OF INTENTION TO PLUG WELL	XX	NOTICE OF INTENTION TO PLUG BACK		NOTICE OF INTENTION TO SET LINER	
NOTICE OF INTENTION TO SQUEEZE		NOTICE OF INTENTION TO ACIDIZE		NOTICE OF INTENTION TO SHOOT (Nitro)	
NOTICE OF INTENTION TO GUN PERFORATE		NOTICE OF INTENTION (OTHER)		NOTICE OF INTENTION (OTHER)	

OIL CONSERVATION COMMISSION
SANTA FE, NEW MEXICOHobbs, New Mexico
(Place)October 13, 1958
(Date)

Gentlemen:

Following is a Notice of Intention to do certain work as described below at the.....

SINCLAIR OIL & GAS COMPANY **STATE 245** Well No. **6** in **B**
(Company or Operator) **Lease** (Unit)

NW 1/4 **SE** 1/4 of Sec. **33**, T. **13S**, R. **33E**, NMPM., **Lamy "J" Pown.** Pool
(40-acre Subdivision)

Lea County.

FULL DETAILS OF PROPOSED PLAN OF WORK

(FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS)

TD 9697FB

13 3/8"OD Casing @ 316' w/ 350 Sk. Cement Circulated

8 5/8"OD do 4084' w/ 1700 Sk. - Top cement behind 8 5/8"OD Casing @ 785'

5 1/2"OD do 9698' w/ 250 Sk. - do 5 1/2"OD " 8747'

Perforations 9602- 9674'

Reason for Plugging- Production depleted

FOLLOWING PROPOSED PLUGGING PROCEDURE:

Spot 25 Sk. Cement plug f/ 9492 to 9697' keeping hole full heavy mud

Run Magnetector and cut 5 1/2"OD Casing @ Approx. 8747' pull- do

Spot 25 Sk. cement plug in top of 5 1/2"OD Casing Stub & 25 Sk. plug f/ 4040 to 4122'

Run Magnetector and cut 8 5/8"OD Casing @ Approx. 785' and pull - keeping hole full heavy mud do

Spot 25 Sk. cement plug in stub of 8 5/8"OD Casing, do

Spot 25 Sk. cement plug f/ 306 to 337' filling hole w/ heavy mud & set 15 Sk. cement plug in

bottom of cellar & top of 13 3/8"OD Casing w/ 4" Regulation Marker extending 4' above surface

level- Fill cellar & Level location, plugging & abandoning operation complete

Approved....., 19.....
Except as follows:Sinclair Oil & Gas Company
Company or Operator

By.....

Position..... Dist. Supt.
Send Communications regarding well to:Approved
OIL CONSERVATION COMMISSION

By.....

Name..... C. C. Salter, 520 E. Broadway

Title.....

Address..... Hobbs, N.M.