	7-4		~~	•
COPIES RECEIVED		•	5	
			>	Form C-103 Supersedes Old
AFE	NEW MEYICO OF	U CONSERVATION CONTRA	•	C-102 and C-103
155	NEW MEXICO OF	IL CONSERVATION COMMISSION		Effective 1-1-65
.s.		Aug 17 0 M 165	, r	a. Indicate Type of Lease
) OFFICE				State Fee Fee
RATOR			-	State Oil & Gas Lease No.
HATOR				. Sidie Off & Gos Ledse No.
SUNDR	Y NOTICES AND DEPOR	OTS ON WELLS		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)				
		/		. Unit Agreement Name
OIL GAS WELL	OTHER- DRY H	HOLE		
Name of Operator				B. Farm or Lease Name 🚜 🛷
PAN AMERICAN PETROLEUM CORPORATION				YOUSTON B
Address of Operator			g), Well No.
30X 68, HOBBS, N. M. 88240				/
Location of Well	200		1	0. Field and Pool, or Wildcat
UNIT LETTER	390 FEET FROM THE S	OUTH LINE AND 330	FEET FROM	NILDCAT PENN
u/aa	10		,	
THE WESTLINE, SECTIO	N TOWNSHIP	12-S RANGE 38	-E NMPM.	

	15. Elevation (Show	whether DF, RT, GR, etc.)] 1	2. County
	11111 GO	187 R. D.D.	<u> </u>	LEA MILLINY
Check A	ppropriate Box To Indi	icate Nature of Notice, Re	port or Other	Data
NOTICE OF IN			BSEQUENT F	
		_	_	30 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -
PERFORM REMEDIAL WORK	PLUG AND ABAND	DON REMEDIAL WORK		ALTERING CASING
TEMPORARILY ABANDON		COMMENCE DRULING OPN	· 🖵 & D	NOW PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT	با ما ماه	Cotto L
		OTHER	DRIMON	allemps
OTHER				•
7. Describe Proposed or Completed Ope	erations (Clearly state all perti	inent details, and give pertinent da	tes, including es	timated date of starting any proposed
_ work) 3EE NOFE 1103.	A			
peroraun ava	naone og D	ttling CIBP	e //, /c	6 4/43x.
Coment Car	//	•		
Jenn: Perforate	el intersella	10000 47 000	7 0 17	110' 11/01005
ent. Performe	- a viceviaco	0842-41, 922-2	1, 943-	48 4 2JSPL.
acidized wf 3000	gal 15% no	Show of Octor	Has.	Set Rix @ 10785
9 500 100 and 1111 11	Mass and		^ .	
	o si eliment.	- egoliacea 10	1.004 - 6	, 18-24, 36-42,
10-76, 100-106, 17,	1-176 W/25PF	. Wudged w	4000	Sal 15/0.
no show I oil a	Eas. Dry T	Holo are water	,·	\mathcal{O}
Danner to Da	3 61			
ropoux to the	g : Wandor	w as foreour	S. Spot !	50 SX Clmens
ur perts: 10/76-000	Shoot & Pull 7	" han apar 7500	2501	in i and a 7" Atril
70-76, 100-106, 17, 20 show I oil of ropool to Plice of Sx @ 4461 fase J.	SE") 1/2	July Offi	NU rey	Note & war & wall
1 2x 6 44611 rase /	JI) KINDLI E A	nues our from ap	p4. 1700	; 25 Sx on and
it I stub: 50 pu	! in + out 1 13	11 CSA 301. 10	Sx @ DU	urlace & week
JA marken n	Tabe Las 11	000000000000000000000000000000000000000	MATE	
A marker. M	wa jorcae	executing and	, www.	- growna
concous.				<i>U</i>
3. I hereby certify that the information e	bove is true and complete to the	he best of my knowledge and belief	•	*
	•			
GNED	TITI	AREA SUPERINTENDEN	T	DATE AUG 6 1969
NAMORE IN A				
-NMOCC-ID		og vieto. Signifika	1987명 - 1	1960
PROVED BY	14 Aprila TITI	LE SUPER NOUR DIST	<u> </u>	DATE
ONDITIONS OF APPROVAL, IF ANY:				 -
11. FS				
WFSpinor				