

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
E-476	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name	
2. Name of Operator		8. Farm or Lease Name	
Amini Oil Corporation		State E - 476 "A"	
3. Address of Operator		9. Well No.	
400 Wall Towers West - Midland, Texas 79701		1	
4. Location of Well		10. Field and Pool, or Wildcat	
UNIT LETTER <u>D</u> , <u>330</u> FEET FROM THE <u>North</u> LINE AND <u>380</u> FEET FROM		Gladiola (Wolfcamp)	
THE <u>West</u> LINE, SECTION <u>30</u> TOWNSHIP <u>12-S</u> RANGE <u>38-E</u> NMPM.			
15. Elevation (Show whether DF, RT, GR, etc.)		12. County	
3886' D.F.		Lea	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11-30-69 Moved in casing pullers.
12-1-69 Set a 30 sx. cement plug inside the 5-1/2" casing @ 9550'. Filled casing with mud.
12-2-69 Shot 5-1/2" casing @ 2758' and pulled casing.
12-3-69 Set a 25 sx. cement plug @ 2758'. 9-5/8" casing set @ 4506'
12-5-69 Set a 10 sx. cement plug in top of 9-5/8" casing and set marker.

Note: The New Mexico Oil Conservation Commission will be notified when the location is cleaned up and ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED John W. Broom TITLE Agent DATE 1-13-70

APPROVED BY John W. Ringman TITLE Geologist DATE JUN 5 1970
CONDITIONS OF APPROVAL, IF ANY: