

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
K-6508
7. Unit Agreement Name
8. Farm or Lease Name
Keith 707 JV-D
9. Well No.
2
10. Field and Pool, or Wildcat
Baum Upper Penn
12. County
Lea

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL <input type="checkbox"/> GAS <input type="checkbox"/> OTHER- Dry Hole
2. Name of Operator
BTA Oil Producers
3. Address of Operator
104 South Pecos, Midland, Texas 79701
4. Location of Well
UNIT LETTER "I" 1980 FEET FROM THE South LINE AND 660 FEET FROM
THE East LINE, SECTION 2 TOWNSHIP 14-S RANGE 32-E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.)
4305 KB

16.

## Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

### SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

## Plugging Procedure:

Set CI BP @ 9800' w/2 sx cement on top.  
Cut & pulled 5-1/2" casing at approximately 8590'±.  
25 sx @ 5 1/2" stub.  
25 sx @ 6500' (Tubb)  
25 sx @ 5400' (Glorietta)  
25 sx @ 4098' (8-5/8" shoe)  
Pull slip joint & 8-5/8" casing @ 2811.  
25 sx @ 2811 (8-5/8" stub)  
25 sx @ 408 (12-3/4" shoe)  
10 sx @ surface.  
Install dry hole marker per NMOCC regulations.  
Verbal approval by Joe Ramey (NMOCC) 4-8-71.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>L. H. Boyce</u>	TITLE <u>Production Clerk</u>	DATE <u>4/19/71</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>SUPERVISOR DISTRICT</u>	DATE <u>APR 21 1971</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

APR 2 1971

OIL CONSERVATION COMM.  
HOUSTON, TEXAS