

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

HOBBS OFFICE O. C. C.
NEW MEXICO OIL CONSERVATION COMMISSION

MAY 31 8 13 AM '68

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No.
723

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>WIW</u>	7. Unit Agreement Name
2. Name of Operator <u>Walter Scott Management Company</u>	8. Farm or Lease Name <u>Trumble</u>
3. Address of Operator <u>922 - 6th Street, Wichita Falls, Texas 76301</u>	9. Well No. <u>4</u>
4. Location of Well UNIT LETTER <u>J</u> , <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>1100</u> FEET FROM THE <u>East</u> LINE, SECTION <u>11</u> TOWNSHIP <u>17</u> RANGE <u>32</u> N.M.P.M.	10. Field and Pool, or Wildcat <u>Galjanar</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>4138 DF</u>	12. County <u>Dea</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6-8-68 Pulled 14 3/8" casing.
Set cast iron bridge plug at 3840' capped w/ 7" sock (7') cmt.
Set 25 sx cmt. at casing stub @ 1506'.
Set 25 sx cmt. @ base of surface pipe.
Set 10 sx cmt. at top of surface.
Set metal marker at well site.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Joann Halsey TITLE Agent DATE July 25, 1968
APPROVED BY John W. Runyan TITLE Inspector DATE 7/25/68
CONDITIONS OF APPROVAL, IF ANY:

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No.
723

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER - Injection Well	7. Unit Agreement Name
2. Name of Operator Ryder Scott Management Company	8. Farm or Lease Name Trimble A
3. Address of Operator 922 - 8th Street, Wichita Falls, Texas 76301	9. Well No. 4
4. Location of Well UNIT LETTER J, 1980 FEET FROM THE South LINE AND 1980 FEET FROM THE East LINE, SECTION 11 TOWNSHIP 17 RANGE 32 NMPM.	10. Field and Pool, or Wildcat Maljamar
15. Elevation (Show whether DF, RT, GR, etc.) 4138 DF	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Work to start on approval (approximately 3-18-68)

We will pull all retrievable tubing, install cast iron bridge plug above top perforations, fill casing and hole with mud-laden fluid, pull casing and install 10 sack cement plug in surface pipe. Erect marker & clean up surface.

1. Cap bridge plug w cement
2. 25 sxs. @ casing stub
3. 25 sxs @ top of salt, if exposed
4. 25 sxs across surface casing shoe
5. 10 sxs @ surface.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Maed Howard TITLE Asst. Prod. Supt. DATE March 11, 1968

APPROVED BY J. A. [Signature] TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: