

NO. OF COPIES RECEIVED		
DISTRIBUTION		
VITA FE		
ILC		
S.G.S.		
AND OFFICE		
PERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDARY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR APPLICATION TO RULE 1103 OR TO APPLY FOR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT TO PRODUCE FROM C-101 FOR SUCH PURPOSES.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator
V-F Petroleum Inc.

Address of Operator
One Marienfeld Place, Suite 580, Midland, TX 79701

Location of Well
UNIT LETTER **A** **330** FEET FROM THE **north** LINE AND **1150** FEET FROM
THE **east** LMC, SECTION **5** TOWNSHIP **16-S** RANGE **38-E** NMPC.

11. Elevation (Show whether DF, RT, GR, etc.)
3753.6' GR

5a. Indicate Type of Lease
State ☒ Fee ☐

3. State Oil & Gas Lease No.
L-5325

7. Unit Agreement Name
NA

8. Farm or Lease Name
Huber-State

9. Well No.
1

10. Field and Pool, or Valued
Denton South-Devonian

12. County
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
REFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
LL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Pull tbg & pkr.
2. Set CIBP @ approx 12,850' & dump 25sx cmt on top of BP.
3. Run free point to see where 5 1/2" csg is free (top cmt @ approx 11,850', calculated).
4. Cut csg @ free point & pull csg out of hole.
5. Run tbg in hole & spot cmt on top of csg stub, as instructed by NMCC.
6. Set plugs in open hole every 3000' and/or as instructed by NMCC. Plugs may be set on certain geological markers.
7. Cut off 8 5/8" csg @ approx 850'. (Top of cmt @ 850' from Temp Survey.)
8. Set plug on stub & base of 12 3/4" csg @ 265' & surface as instructed by NMCC.
9. Set dry hole marker; make location clean up; call NMCC when ready for inspection.

Tops as follows:

Anhydrite	2185'
T. Salt	2275'
B. Salt	3095'
Yates	3208'
Queen	4059'
Grayburg	4645'
San Andres	4935'

San Andres	4935'
Glorietta	6475'
Tubb	7655'
Abo	8375'
Penn	10,570'
Miss	12,030'
Woodford	12,750'
Devonian	12,868'

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Signed By V.F. Vasicek TITLE President & P.E. DATE 8-3-81

Reviewed By Jerry Soren DATE 5 1981

CONDITIONS OF APPROVAL, IF ANY