Form 9-331 (Ma. 1963)

REPAIR WELL

(Other)

UNITED STATES SUBMIT IN TR. DEPARTMENT OF THE INTERIOR (Other instructions on reverse side)

. TCATE*

Form approved. Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

GEOLOGICAL SURVEY	-	<u> </u>	0	00	ک کے	7/	6
V NOTICES AND DEPODES ON WELLS						OTTEE	

GEOLOGICAL SURVEY			166863718-14		
SUNDRY NOTICES (Do not use this form for proposals to Use "APPLICATION"	AND REPORTS (drill or to deepen or plug FOR PERMIT—" for such p	ON WELLS back to a different reservoir. proposals.)	6. IF INDIAN, ALLOTTEE	OR THIBE NAME	
OIL GAS XX OTHER			7. UNIT AGREEMENT NAME LUSK Deep Unit		
2. NAME OF OPERATOR			8. FARM OR LEASE NAM	16.	
El Paso Products Compa	.ny		Lusk Deep /	11.7	
3. ADDRESS OF OPERATOR	· · · · · · · · · · · · · · · · · · ·		9. WELL NO.	nair-	
c/o Hobbs Pipe & Suppl	y Co., Box 20	10, Hobbs, N.M.	3		
 LOCATION OF WELL (Report location clearly See also space 17 below.) 	and in accordance with any	State requirements.	10. FIELD AND POOL, OR	WILDCAT	
At surface		· · · · · · · · · · · · · · · · · · ·	Lusk		
1650' FNL & 6	60' FWL		11. SEC., T., H., M., OR B. SURVEY OR AREA 20-19S-32E	lk. And	
14. PERMIT NO. 15.	ELEVATIONS (Show whether DF	, RT, GR, etc.)	12. COUNTY OR PARISH	13 STATE	
	UK		Lea	N. M.	
16. Check Appropr	iate Box To Indicate N	lature of Notice, Report, or (Other Data	· · · · · · · · · · · · · · · · · · ·	
NOTICE OF INTENTION TO		,	UENT EXPORT OF:		
	R ALTER CASING LE COMPLETE N* XX	WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING	BEPAIRING W ALTERING CA	SING	

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.).

- 1. Propose To Spot a 25 sx cement plug to cover existing perforations.
- 2. Propose to spot a 25 sx cement plug at stub of $5\frac{1}{2}$ " Casing.
- 3. Propose to spot a 25 sx cement plug at 7,000', if this much casing is recovered.
- 4. Propose to spot a 35 sx cement plug at base of 9-5/8" Casing (4552')
- 5. Propost to spot a 25 sx cement plug from 2,400'-2,500'.
- 6. Propose to spot a 25 sx cement plug from 700'- 800'. 7. Propose to spot a 10 sx cement plug in the top.

CHANGE PLANS

8. Hole will be loaded with mud-laden fluids and a 4" regular marker erected.

DATE9/16/7	71
OVED DATE	
_	OVED

SEP 17 1971

F VED

ST: 211971

OL CONSESSED AT THE COLOR