

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions on
reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.
LC 058697(6)
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. NAME OF OPERATOR
CONTINENTAL OIL COMPANY
3. ADDRESS OF OPERATOR
Box 460, Hobbs, N.M. 88240
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
1980' FSL & 1980' FWL OF SEC. 30
14. PERMIT NO.
15. ELEVATIONS (Show whether DF, RT, GR, etc.)
4046' DF

7. UNIT AGREEMENT NAME
MCA
8. FARM OR LEASE NAME
MCA UNIT
9. WELL NO.
199
10. FIELD AND POOL, OR WILDCAT
MALJ. G-SA REPRESS.
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
SEC. 30, T-17S, R-22E
12. COUNTY OR PARISH
LEA
13. STATE
N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐ PULL OR ALTER CASING ☒
FRACTURE TREAT ☐ MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐ ABANDON* ☐
REPAIR WELL ☐ CHANGE PLANS ☐
(Other) **INSTALL CASING** ☒

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐ REPAIRING WELL ☐
FRACTURE TREATMENT ☐ ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐ ABANDONMENT* ☐
(Other) ☐
(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Tubing was found to be stuck from either scale build-up or collapsed csq. It is proposed to enter the well to determine downhole conditions. If csq. is collapsed, the following procedures are proposed: Clean out as well as possible & run open hole caliper. If csq. collapsed, run 4 1/2" 9.5# k-55 csq either as liner or full string. If liner set, cmt w/85 sks. Class "C" cmt. set pack-off & apply squeeze w/last 15 sks. If full string required, cmt w/250 sks. Class "C" - then follow w/85 sks. Class "C". WOC 18 hrs, drill out plug & clean out to 4248'. Treat for scale. Restore production.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

DATE

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

11545-5, MCA-1, File