

|                        |  |
|------------------------|--|
| NO. OF COPIES RECEIVED |  |
| DISTRIBUTION           |  |
| SANTA FE               |  |
| FILE                   |  |
| U.S.G.S.               |  |
| LAND OFFICE            |  |
| OPERATOR               |  |

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

|  |  |
|--|--|
| 5a. Indicate Type of Lease<br>State <input checked="" type="checkbox"/> Fee <input type="checkbox"/> |  |
| 5. State Oil & Gas Lease No.<br>E-792  |  |
| 7. Unit Agreement Name   |  |
| 8. Farm or Lease Name<br>Cockburn-Magolia-St.  |  |
| 9. Well No.<br>1   |  |
| 10. Field and Pool, or Wildcat<br>Corbin-Queen   |  |
| 12. County<br>Lea  |  |

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

|   |
|---|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>                                  |
| 2. Name of Operator<br>BTA Oil Producers  |
| 3. Address of Operator<br>104 South Pecos, Midland, Texas 79701   |
| 4. Location of Well<br>UNIT LETTER "A" 660 FEET FROM THE North LINE AND 660 FEET FROM<br>THE East LINE, SECTION 16 TOWNSHIP 18-S RANGE 33-E NMPM. |
| 15. Elevation (Show whether DF, RT, GR, etc.)<br>3882' GL   |

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐  
OTHER ☐

PLUG AND ABANDON ☒  
CHANGE PLANS ☐  
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOBS ☐  
OTHER ☐  
ALTERING CASING ☐  
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

### Plugging Procedure:

Set CIBP @ 4175' w/2 sx cmt on top  
Cut & pull 5½" csg  
25 sx @ 5½" stub  
25 sx @ 1570' (8-5/8" shoe)  
Cut & pull 8-5/8" csg  
25 sx @ 8-5/8" stub  
25 sx @ 235' (10" shoe)  
10 sx @ surface  
Install dry hole marker per NMOCC regulations  
Verbal approval by Joe Ramey (NMOCC-Hobbs) on 9-22-71

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Joe D. Ramey TITLE Production Clerk DATE 12/7/71

Signed by  
Joe D. Ramey  
Dist. 1, Supv.

APPROVED BY \_\_\_\_\_ DATE DEC 9 1971

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

DEC 6 1971

OIL CONSERVATION COMM.  
HOBBBS, N. M.