

NO. OF COPIES RECEIVED

DISTRIBUTION

ANTAFE

FILE

U.S.G.S.

LAND OFFICE

OPERATOR

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease

State ☒Fee ☐

5. State Oil & Gas Lease No.

B-1520

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1.

OIL
WELL ☒

GAS

WELL ☐OTHER ☐

2. Name of Operator

Mobil Oil Corporation

3. Address of Operator

Box 633, Midland, Texas 79701

4. Location of Well

UNIT LETTER L 660 FEET FROM THE West LINE AND 1920 FEET FROM
THE South LINE, SECTION 12 TOWNSHIP 17S RANGE 34-E NMPM.

7. Unit Agreement Name

8. Form or Lease Name

Bridges State

9. Well No.

77

10. Field and Pool, or Wildcat

Vac (S-LA)

15. Elevation (Show whether DF, RT, GR, etc.)

4023 Gr.

12. County

Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐TEMPORARILY ABANDON ☐PULL OR ALTER CASING ☐OTHER ☐PLUG AND ABANDON ☒CHANGE PLANS ☐REMEDIAL WORK ☐COMMENCE DRILLING OPNS. ☐CASING TEST AND CEMENT JOBS ☐OTHER ☐ALTERING CASING ☐PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plug & abandon as per attached recommendation

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED

TITLE

DATE

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

by
Joe D. Ramey
Dist. I, Supv.

JAN 16 1973

MIDLAND E & P DIVISION

WELL WORK RECOMMENDATIONS


Proposals for Well Reconditioning and Subsurface Maintenance
Workovers, Expense DD's, PB's, and Conversions

Lease: Bridges State Well No. 77
Field: Vacuum-San Andres Flood
County: Lea State: New Mexico

RECOMMENDED PROCEDURE:

1. Run 2" Tubing w/ cement retainer. Set retainer @ 4630' & squeeze San Andres perfs (4686'-4712').
2. Circulate hole to mud laden fluid.
3. Spot 20 sx cement plug from 1615' to 1715'.
4. Spot 10 sx cement plug at surface.
5. Cut off well head and install marker.

DIAGRAMATIC WELL SKETCH
BRIDGES STATE N: 77
VACUUM - GRAYBURG - SAN ANDRES
LEA COUNTY - NEW MEXICO.



NO TUBING IN THE HOLE