

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-73

RECEIVED	
DISTRIBUTION	
DATE	
BY	
OFFICE	
NAME	

5a. Indicate Type of Lease	State ☒ Fee ☐
5. State Oil & Gas Lease No.	B-1733

SUNDARY NOTICES AND REPORTS ON WELLS
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.

☒ OIL WELL ☐ GAS WELL ☐ OTHER

Name of Operator
XACO Inc.

Address of Operator
P.O. Box 728, Hobbs, N.M. 88240

Location of Well

UNIT LETTER B 669 FEET FROM THE North LINE AND 1980 FEET FROM

THE East LINE, SECTION 1 TOWNSHIP 18S RANGE 34E N.M.P.M.

15. Elevation (Show whether DF, RT, GR, etc.)

7. Unit Agreement Name
Vacuum Grayburg San Andres Unit

8. Form or Lease Name

9. Well No.
57

10. Field and Foot, or Wharfed
Vacuum Grayburg San Andres

12. County
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☒
TEMPORARILY ABANDON ☐
REPAIR OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐
OTHER ☐

REMEDIAL WORK ☐
COMMENCE DRILLING OPERATIONS ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐
OTHER ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rig up. Pull rods. Install BOP.
2. Circ. hole clean
3. Set pkr. at 3930'.
4. Acidize open hole w/15,000 gal. of 15% gelled NEFE mixed w/10 gal. of scale inhibitor in 3 stages, using 500# RS and 500# of crushed moth balls in gelled brine.
5. POH w/pkr.
6. Run production equipment and return to production and test.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W.B. Lyle TITLE Dist. Opr. Mgr. DATE 5/23/85

ORIGINAL SIGNED BY ROBERT LAY

APPROVED BY _____ DATE MAY 30 1985

CONDITIONS OF APPROVAL, IF ANY: