

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SALE PRICE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REOPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT TO DRILL C-101 FOR SUCH PROPOSALS.)

1. ☐ OIL WELL ☐ GAS WELL ☐ OTHER- **Temporarily Abandon**

2. Name of Operator
Murphy H. Baxter

3. Address of Operator
P. O. Box 2040 Midland, Texas 79702

4. Location of Well
UNIT LETTER **N** **990** FEET FROM THE **South** LINE AND **1509.71** FEET FROM
THE **West** LINE, SECTION **6** TOWNSHIP **18S** RANGE **34E** N.M.P.M.

5a. Indicate Type of Lease
State ☒ Free ☐

5. State Oil & Gas Lease No.
E8714

7. Unit Agreement Name
N. EK Queen Unit

8. Farm or Lease Name
Tract 4

9. Well No.
3

10. Field and Pool, or Wildcat
EK Yates 7 Rivers Que

12. County
Lea

13. Elevation (Show whether DF, RT, GR, etc.)
4090 GR

6. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

*Commission will be notified 24 hrs. prior to commencing work.

1. CIBP. has been set @ 4100'. (4-9-84)
2. Spot 35' of cement on top of CIBP.
3. Displace hole with mud-laden fluid. Close pipe rams. Test plug and casing to 500#'s.
4. Perforate 4 holes @ 1680'. (Top of anhydrite @ 1710'.) Circulate or squeeze 50 sks. or sufficient cement to isolate anydrite section. WOC.
5. Tag and test plug in casing to 500#'s.
6. Spot cement 50' above and below surface casing shoe @ 329'. WOC.
7. Tag plug. Cut off bradenhead and weld steel plate on casing. Set P & A marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Chuck Sledge TITLE Petroleum Engineer DATE 8-13-87

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

COPIED BY _____ TITLE _____ DATE AUG 25 1987

ADDITIONS OF APPROVAL, IF ANY:

RECEIVED
AUG 24 1987
OCD
HOBBS OFFICE