

DEPTHDEGREES OF DEVIATION

3950	2-3/4
4015	2-1/2
4075	2-1/4
4140	2-3/4
4200	2-1/2
4265	2-3/4
4325	2-1/2
4390	2-1/2
4480	2-3/4
4580	2-3/4
4670	2-3/4
4760	2-3/4
4860	3-1/2
4890	3
4985	3-1/4
5048	3-1/4
5140	3-1/4
5205	3-1/2
5265	3
5360	3-1/2
5418	2-3/4
5520	3-3/4
5550	3-1/4
5610	3-1/4
5700	3-1/4
5795	3-1/2
5890	3-3/4
5950	3-1/2
6015	4
6045	4
6110	3-3/4
6170	4
6230	3-3/4
6290	4
6355	3-3/4
6420	3-3/4
6510	3-3/4
6575	4
6637	4-1/4
6700	4
6760	4
6825	3-3/4
6887	4
6950	4
7025	3-3/4
7095	3-3/4
7150	3-1/4
7225	3-1/4
7270	3-1/4
7335	3-1/2