

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
HOBBBS NEW MEXICO 88240

Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM-63026

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

TONTO WEST 7 FEDERAL

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat (Queen-Penrose Test)

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

W $\frac{1}{2}$ Sec. 7, T-19S, R-33E

12. COUNTY OR PARISH

Lea

13. STATE

New Mexico

1. OIL ☒ GAS ☐ OTHER ☐
WELL WELL

2. NAME OF OPERATOR

MURPHY OPERATING CORPORATION

3. ADDRESS OF OPERATOR

P. O. Drawer 2648, Roswell, New Mexico 88201

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface

660' FNL & 660' FWL, (Unit Ltr. D)

14. PERMIT NO.

15. ELEVATIONS (Show whether OF, RT, GR, etc.)

3665.3' G. R.

NOV 08 1985

HOBBBS NEW MEXICO

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Cementing 5 $\frac{1}{2}$ " long string

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

10-30-85 Built location & moved in rig & rigged up L&M Drilling Rig #1.

10-31-85 Brine Wtr. arrived @ 1:00 P.M. Filled pits & mixed mud, Visc. 35. Spud - 2:00 P.M. drlg. top plug. TIH & picked up D.C. @ 270'. At 6:30 P.M. picked up & reamed to 450' hole sluffing. Mixed mud Visc. 40, W.L. 20. At 9:00 P.M. depth @ 765' hole sluffing, Red Bed unstable, mixed mud visc. 50, W.L. 10, Circ. & continued hole. Drlg. plug @ 800' @ depth 1260'.

11-1-85 Drlg. depth @ 1260' @ 7:00 A.M. Had to ream & wash to 2400' using Kelly on every jt. At 4:00 P.M. started picking D.P. with pickup line, hit plugs @ 3667' & 3767'. Drlg. plug., picked up D.P., using Kelly & reamed & washed. 4465' Depth @ 11:00 P.M.

11-2-85 Drlg. depth @ 4500' w/bit #1, 7-7/8" Smith F-57, Jets 13-13-14. Made 35' new hole, hole cleaning up. Pit full of cuttings. TOH to jet pit, change bit. Jetted pit & added 320 bbls. brine. Mud up same to 48 Visc., 12 W.L., M.W. 10.2#, WOB 35#. TIH w/new bit #2 to 4560', J-7 Milltooth 7-7/8" Smith HTC, Jets 12-12-13. Drlg. time 7 hrs, reamed 17 hrs. = 24 hrs.

CONTINUED ON PAGE 2 - OVER

I hereby certify that the foregoing is true and correct

SIGNED

Lois N. Brown
Lois N. Brown

TITLE Production Records

DATE Nov. 7, 1985

(This space for Federal or State office use)

ACCEPTED FOR RECORD

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

NOV 22 1985

*See Instructions on Reverse Side