

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025-30717

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
857948

7. Lease Name or Unit Agreement Name
VACUUM GRAYBURG SAN ANDRES UNIT

8. Well No.
157

9. Pool name or Wildcat
VACUUM GRAYBURG SAN ANDRES

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
TEXACO PRODUCING INC.

3. Address of Operator
P. O. Box 3109 Midland, Texas 79702

4. Well Location
Unit Letter C : 710 Feet From The NORTH Line and 2530 Feet From The WEST Line

Section 1 Township 18-SOUTH Range 34-EAST NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
GR-3993', KB-4006'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: COMPLETION ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIRU DA&S. CLEAN OUT TO PBTD OF 4990'.
2. PENWOOD RAN GR-CNL-CCL FROM 4990' TO 3990'. PERF w/ 2 JSPF: 4436-42, 4446-50, 4455-60, 4464-74, 4496-4509, 4525-39, 4547-55, 4562-68, 4664-70, 4676-80. 152 HOLES. WESTERN ACIDIZED w/ 7500 GAL 15% NEFE. TIH w/ RBP. SET @ 4390' & TEST TO 3000#.
2. PENWOOD PERF w/ 2 JSPF: 4282-84, 4291-93, 4300-08, 4313-16, 4320-31, 4344-48. 60 HOLES. WESTERN ACIDIZED w/ 4000 GAL 15% NEFE. SWAB 7 HRS. REC 7 BNO, 6 BW & 178 BLW. MOVE RBP TO 4268'. TEST TO 3000#.
3. PERF w/ 2 JSPF: 4178-82, 4194-98, 4204-12, 4230-41, 4254-58. 62 HOLES. WESTERN ACIDIZED w/ 4100 GAL 15% NEFE. SWAB 7 HRS. REC 5 BNO & 47 BLW.
4. TOH WITH RBP. RAN 2 7/8 TUBING AND SUB PUMP. SEATING NIPPLE @ 4880'.
5. PUMP 24 HOURS ON POTENTIAL TEST. RECOVERED 34 BNO & 797 BW.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE C.P. Basham / cwh TITLE DRILLING SUPERINTENDENT DATE 08-21-90

TYPE OR PRINT NAME C. P. BASHAM

TELEPHONE NO. 915-6884620

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: