

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-20949
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-1056-1
7. Lease Name or Unit Agreement Name NEW MEXICO "Q" STATE
8. Well No. 8
9. Pool name or Wildcat VACUUM GLORIETA
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4009' KB

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator  
Texaco Exploration and Production Inc.

3. Address of Operator  
P. O. Box 730 Hobbs, NM 88240

4. Well Location  
Unit Letter J : 1800 Feet From The SOUTH Line and 2100 Feet From The EAST Line  
Section 25 Township 17-S Range 34-E NMPM LEA

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
<b>NOTICE OF INTENTION TO:</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. NOTIFIED NMOCD. MIRU ON GLORIETA STRING, TOH W/ RODS & PMP, INSTALLED BOP, TOH W/ TBG. TIH W/ KUT RITE SHOE TO 6527'. STARTING DATE 7/27/93
2. RU ON BLINEBRY STRING, ATTEMPTED TO FISH STUCK RBP @ 4015' WITHOUT SUCCESS. DRILLED OUT TO 4016', FISHED AGAIN AND RECD RBP. CLEANED OUT TO 6595'.
3. IN GLORIETA STRING SET CIBP @ 6530' & CAPPED W/ 35' CMT.
4. IN BLINEBRY STRING, CAPPED CIBP @ 6530' W/ 35' CMT.
5. ESTD CIRC, PUMPED CMT TO SURF IN BOTH STRINGS.
6. CUT OFF WELLHEAD & ANCHORS, INSTALLED DRY HOLE MARKER, CLEANED LOCATION. COMPLETION DATE 10/26/93.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Monte C. Duncan TITLE ENGINEER'S ASSISTANT DATE 11-8-93  
TYPE OR PRINT NAME MONTE C. DUNCAN TELEPHONE NO. 393-7191

(This space for State Use)

APPROVED BY Carmy W. Hill OIL & GAS INSPECTOR DATE JAN 26 1994  
CONDITIONS OF APPROVAL, IF ANY:

5117