

NEW MEXICO STATE LAND OFFICE
SANTA FE, NEW MEXICO
DEPARTMENT OF THE STATE GEOLOGIST
SANTA FE

NOTICE OF INTENTION TO ABANDON WELL

Notice must be given at least five days before work is to begin to the State Geologist or to the proper Oil and Gas Inspector. It is desirable that a representative of the Department of the State Geologist witness the plugging of wells being abandoned whenever possible. If changes in the proposed plan are considered advisable, a copy of this notice showing such changes will be returned to the sender. Submit this notice in duplicate.

Artesia, N. Mex., 8-22 1931

Mr. E. H. Wells
Santa Fe, New Mexico.

Dear Sir:

You are hereby notified that it is our intention to abandon State Well
No. 1 in NE NE of Sec. 16 Twp. 20 S, Rge. 32 E,
N. M. P. M., Oil Field, Lea County.
We plan to commence work on August 26th, 1931.

The reasons for wishing to abandon the well are as follows:

Drilled to 4000 feet, drilled into water

The present condition of the well is as follows:

Set 455' - 15 1/2" pipe
" 935' - 12 1/2" pipe, cemented with 25 sacks cement
" 2424' - 8 1/2" pipe, " " 25 sacks cement
" 3208' 3" - 6-5/8" pipe
Three thousand feet water in hole.

The work which we propose to do in abandoning the well is as follows:

Fill up to bottom of 6-5/8" pipe with heavy mud and dump 25 sacks of cement. After pulling 6-5/8" pipe, fill hole with heavy mud to top of salt and dump 25 sacks cement. After pulling balance of pipe, fill hole with heavy mud and set regulation marker in cement.

Sincerely yours,

Approved August 22 1931
Except as follows:

WESTERN DRILLING & ENG. CO.,

Company or Operator.

By [Signature]
Position Secretary

Send communications regarding this well to

Name Western Drilling & Eng. Co.,

Address Artesia, N. M.

[Signature]
State Geologist or Oil and Gas Inspector.