

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease  
State  For

5. State Oil & Gas Lease No.  
E-5885

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.

1.  OIL WELL  GAS WELL  OTHER- Water Injection Well

2. Name of Operator  
GULF OIL CORPORATION

3. Address of Operator  
P. O. Box 670, Hobbs, NM 88240

4. Location of Well  
UNIT LETTER P 660 FEET FROM THE South LINE AND 660 FEET FROM THE East LINE SECTION 30 TOWNSHIP 19S RANGE 35E

7. Unit Agreement Name  
West Pearl Queen Unit

8. Farm or Lease Name  
Pearl Queen

9. Well No.  
131

10. Field and Pool, or Wildcat  
Pearl Queen

11. Elevation (Show whether DF, RT, GR, etc.)  
3742' GL

12. County  
Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <u>Fshd bad tbg, set CIBP &amp; TA'd</u> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

PU OS on 2-3/8" tbg; caught fish, POH, LD 48 jts 1 1/2" tbg & seal assy. Attempted to catch pkr, unable to catch pkr. WIH w/4 1/2" CIBP, plug W/N set. Redressed setting tool; WIH w/4 1/2" CIBP, plug W/N set. Started out of hole w/plug, hung up @ 2700' f/surf. Pulled line out of rope socket. WIH, caught fish (4769'). POH, LD fish. Set 4 1/2" CIBP @ 4760'. WIH w/2-3/8" tbg open-ended. Circ 4 1/2" csg w/treated fresh wtr pkr flu. Pulled & LD all 2-3/8" tbg. Left pkr & 2 jts 2-3/8" tail pipe below CIBP. ND BOP, RD PU. Well TA.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A. B. Wikes, Jr. TITLE Area Engineer DATE 4-21-80

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: \_\_\_\_\_