

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL NO.	5J-025-03278
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	E-5886
7. Lease Name or Unit Agreement Name	West Pearl Queen Unit
8. Well No.	151
9. Pool name or Wildcat	Pearl Queen
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3720' GL

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL GAS WELL OTHER TA-Oil Well

2. Name of Operator
Pyramid Energy, Inc.

3. Address of Operator
10101 Reunion Place, Ste. 210 San Antonio, TX 78216

4. Well Location
Unit Letter E : 1980 Feet From The North Line and 660 Feet From The West Line
Section 32 Township 19S Range 35E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3720' GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

05/25/94 Tagged CIBP at 4480' and circulated hole with mud. Spotted 25 sack cement
to plug on top of CIBP. Spotted 25 sack cement plug at 1900'. Perforated 4
05/26/94 holes at 190'. Pumped 85 sacks cement down 4 1/2" casing through perfs at
190'. Circulated cement back to surface between 4 1/2" and 8 5/8" casings.
Left cement plug inside 4 1/2" casing from surface to 190'. Cut off casing
3' below ground level and weld on cap and marker. Well plugged and abandoned
05/26/94.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Scott Graef TITLE Operations Manager DATE 06/01/94
 TYPE OR PRINT NAME Scott Graef TELEPHONE NO. (210)308-8000

(This space for State Use)

APPROVED BY Carry W. Hill TITLE OIL & GAS INSPECTOR DATE _____
 CONDITIONS OF APPROVAL, IF ANY:

JCS

dp

RECEIVED

JUN 10 1991

FOOD STUDIES
OFFICE