## NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

HOBBS OFFICE OCC

## -MISCELLANEOUS REPORTS ON WELLS

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is comed. It should be signed and filed as a report on Beginning Drilling Operations. Results of test of control of the control of the control of test of of te

pleted. It should be signed and filed as result of well repair, and other impor instructions in the Rules and Regulati	tant operations, even though th	ne work was witnessed	by an agent of the Commissio	n. See additional	
instructions in the react and response	Indicate Nature of Re	eport by Checking Bel	low		
REPORT ON BEGINNING DRILLING OPERATIONS	REPORT ON RES		REPORT ON REPAIRING WELL		
REPORT ON RESULT OF PLUGGING WELL	REPORT ON RECOPERATION	OMPLETION	REPORT ON (Other)		
	May (Dat	17, 1954	Hebbs, H	Place)	
Following is a report on the wo	rk done and the results obtain	ed under the heading r	noted above at the		
(Company or Operator)			R. R. Bell "H"	······································	
,, ,	termire	, Well No	in the <b>SE</b> 1/4 <b>NE</b> 1/4	of Sec23,	
T 19-8 , R 36-E , NMPM.,	Eumont Gas	Pool,	<u>lea</u>	County.	
The Dates of this work were as follows:	Dates of this work were as follows: May 15, 1954				
Notice of intention to do the work	(was not) submitted on For	m C-102 on	(Cross out incorrect words)	, 19,	
and approval of the proposed plan	as) (was not) obtained.				
DET	AILED ACCOUNT OF WOR	K DONE AND RESU	LTS OBTAINED		
Dillard and Waltermire	spudded 12-1/4" hole	1:30AM 5-15-51	i•		
1					
				•	
Witnessed by J. E. Sneed	Gulf Oil	Corporation	Drilling Fores	a.an	
(Name	2)	(Company)	(Title)		
Approved:			at the information given above is	true and complete	
OIL CONSERVATION	N COMMISSION	to the best of my	knowledge,		
J. J. Stay Co. (Nam	<u> </u>	Name			
/	, ,	Position	Area Prod. Supt.	bd an	
53 11 12 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	MAY	Representing	Max 2167, Hebbs		
(Title)	(Date)	Address			