

NO. OF COPIES RECEIVED		
DISTRIBUTION		
ANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

<p>SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)</p>		<p>5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/></p> <p>5. State Oil & Gas Lease No.</p>
<p>OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/></p> <p>Name of Operator Amerada Hess Corporation</p> <p>Address of Operator Drawer "D", Monument, New Mexico 88265</p> <p>Location of Well UNIT LETTER L 660 FEET FROM THE West LINE AND 1980 FEET FROM THE South LINE, SECTION 25 TOWNSHIP 19-S RANGE 36-E NMPM.</p>		<p>7. Unit Agreement Name</p> <p>8. Farm or Lease Name W.A. Weir "A"</p> <p>9. Well No. 1</p> <p>10. Field and Pool, or Wildcat Eunice-Monument (G-SA)</p>
<p>15. Elevation (Show whether DF, RT, GR, etc.)</p>		<p>12. County Lea</p>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plan to: Run GR-N logs and plug back from T.A. G-SA oil zone with bridge plug and cement. Perforate G-SA gas interval, stimulate with 15% acid. Run production equipment and restore well to producing status.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

ED *John Runyan* TITLE Supver., Admin. Services DATE 5-8-75
 ORG. Signed by John Runyan
 Geologist TITLE _____ DATE MAY 12 1975
 APPROVED BY _____
 CONDITIONS OF APPROVAL, IF ANY: