

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
PIERCE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

3-NMOCD
 1-File

5a. Indicate Type of Lease
 State For
 5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
 USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.

1. OIL WELL GAS WELL OTHER- P & A

2. Name of Operator
 Apollo Oil Company

3. Address of Operator
 P. O. Box 1737, Hobbs, NM 88240

4. Location of Well
 UNIT LETTER D 660 FEET FROM THE North LINE AND 660 FEET FROM
 THE West LINE, SECTION 33 TOWNSHIP 19 RANGE 36 NMPLA.

7. Unit Agreement Name
 8. Form of Lease Name
 Record "A"
 9. Well No.
 1
 10. Field and Pool, or Wellnet
 Eumont

15. Elevation (Show whether DF, RT, GR, etc.)
 3664.0'

12. County
 Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 110.

- 12/22/80 RU Baber Well Service.
- 1/8/81 Ran Compensated Neutron Gamma Ray Log from 3430-1430'. Attempts to proceed as planned were unsuccessful.
 Per verbal approval to plug and abandon from Mr. Jerry Sexton, ran drill pipe open ended to first of the four cement plugs. Laid a 25 sx cement plug at 3427'.
- 1/9/81 Tagged top of cement at 3306'. Pulled up to 2210'. Spotted 30 sxs. Waited 3 hrs. TIH and tagged at 2600'. Laid down 1160' tbg. Mixed 2 sxs of paper and 50 sx plug. POH. SD.
- 1/10/81 Tagged top of cement at 1046'. Pulled up to 160'. Spotted 50 sx plug. Put 10 sx top hole plug. Rigged down. Installed dry hole marker, and covered up pits and cleaned up location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Mohammed Yamin Merchant TITLE Consulting Engineer DATE 1/12/81

APPROVED BY [Signature] TITLE OIL & GAS INSPECTOR DATE JAN 11 1981

CONDITIONS OF APPROVAL, IF ANY: