

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Amerada Hess Corporation	8. Farm or Lease Name J. R. Phillips
3. Address of Operator Drawer D, Monument, New Mexico 88265	9. Well No. 7
4. Location of Well UNIT LETTER <u>H</u> <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>760</u> FEET FROM THE <u>East</u> LINE, SECTION <u>1</u> TOWNSHIP <u>20S</u> RANGE <u>36E</u> NMPM.	10. Field and Pool, or Wildcat Monument Abo
15. Elevation (Show whether DF, RT, GR, etc.) 3578' DF	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plan to MIRU PU, fish parted rods & pull rods, pump, & tbg. Run CIBP & set BP at 7130' & spot 4 sks. cement on top of BP. Perf. Upper Abo Zone 5-1/2" csg. selectively fr. 6912' to 7095' w/2 SPF using 4" csg. gun. TIH w/pkr. & tbg. & acidize Abo Zone 5-1/2" csg. perf. fr. 6912' to 7108' w/2500 gal. 20% NEFE HCL acid. Swab load. Pull tbg. & pkr. Re-run pkr. & tbg. & resume prod. as gas well in oil pool.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED R. C. Wheeler, Jr. TITLE Supv. Adm. Avc. DATE 4-28-87

ORIGINAL SIGNED BY JERRY SIXTON
DISTRICT 1 SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

APR 30 1987