

OIL CONSERVATION COMMISSION

HOBBS, NEW MEXICO

April 18, 1957

C
O
P
Y

Continental Oil Co.
Box 427
Hobbs, New Mex.

Gentlemen:

Mr. W. A. Gressett has made an inspection of the location for your Leonard Oil Co. et al No. 2 in Unit I of Section 9, T-20-S, R-36-E and has found that the inscription on the marker shows only NE/4 9-20-36 rather than NE SE 9-20-36 as it should.

Prompt approval will be made of your Report of Final Plugging when this has been corrected.

Yours very truly,

OIL CONSERVATION COMMISSION

R. F. Montgomery
Proration Manager

mc