

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer 00, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.	30-025-04365
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	MAGRUDER STATE
8. Well No.	3
9. Pool name or Wildcat	74103 <i>ELMONT</i> <i>Y-SR-120</i>

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator HAWKINS OIL & GAS INC.
3. Address of Operator 400 S. BOSTON SUITE 800 TULSA OK. 74103
4. Well Location Unit Letter <u>P</u> : <u>660</u> Feet From The <u>SOUTH</u> Line and <u>990</u> Feet From The <u>EAST</u> Line Section <u>28</u> Township <u>20 S</u> Range <u>36 E</u> NMPM LEA County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: _____ <input type="checkbox"/>		OTHER: _____ <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-9-97 MOVE IN P & A EQMT. R.U. UNIT.
 10-10-97 LAY DOWN ROD. PULL TBG. SET 7" CIBP AT 3600' DUMP BAIL 5 SX ON TOP.
 10-10-97 RAN IN HOLE W/TBG. CIRC HOLE W/MUD L. FLUED. PULL UP HOLE TO 1634'
 10-10-97 PERF AT 1825'. SQUEEZE 25 SX CMT DISPL TO 1725' TAG AT 1720'
 10-13-97 L.D. TBG. PERF AT 368'. CIRC HOLE W/140 SX CMT DOWN 7" & 7" X 8 5/8 CASING.
 10-13-97 RIG DOWN P & A EQMT. INSTALL DRY HOLE MARKER.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *Jimmy Bagley* TITLE PLUGGING SUPERVISOR DATE 10-13-97
 TYPE OR PRINT NAME JIMMY BAGLEY TELEPHONE NO. 915 530-0907

(This space for State Use)

APPROVED BY *Charles Lewis* TITLE OIL & GAS INSPECTOR DATE JUN 06 1997
 CONDITIONS OF APPROVAL, IF ANY: J.C.