

OIL CONSERVATION DIVISION
 P. O. BOX 2088
 SANTA FE, NEW MEXICO 87501

Form C-101
 Revised 10-1-7

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
 State Fee
 5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
 USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.

OIL WELL GAS WELL OTHER

Name of Operator
 Chevron U.S.A. Inc.

Address of Operator
 P.O. Box 570 Hobbs, NM 88240

Location of Well

UNIT LETTER M 660 FEET FROM THE South LINE AND 660 FEET FROM THE West LINE. SECTION 36 TOWNSHIP 20S RANGE 36E NMPM.

7. Unit Agreement Name
 Eunice Monument South

8. Farm or Lease Name
 Unit

9. Well No.
 166

10. Field and Pool, or Wildcat
 Eunice Monument GB/S

15. Elevation (Show whether DF, RT, GR, etc.)
 3552

12. County
 Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
 NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

OR REPAIR REMEDIAL WORK
 TEMPORARILY ABANDON
 OR ALTER CASING
 OTHER

PLUG AND ABANDON
 CHANGE PLANS

REMEDIAL WORK
 COMMENCE DRILLING OPNS.
 CASING TEST AND CEMENT JOB
 ALTERING CASING
 PLUG AND ABANDONMENT
 OTHER sqz zones 1 & 2 recomp zones 2 & 3

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Work performed 6-29-88 thru 7-8-88 TD: 4037 PB: 4020

TOH w/ production equipment. Set CICR at 3830, cmt w/200sx Cl C, displace w/ CBW. Rev out 0 sx, to surface, 196 sx below ret. WOC 24 hrs. Sting into CICR at 3830, pumped 100sx Cl C, rev out 15 sx cmt. WOC 20 hrs. Drlg cmt to 3830, drlg CICR to 3833. Circulate clean. Drlg. cmt 3833 - 3995, circ. clean. Swab, Drlg on CICR at 3995, circ clean. Drlg. cmt rtnr and cmt to 4020', circ and displace w/CB. Perf 3982-88, 4002-12 w/ 2 1/8" guns, 1 SPF, 180° phase, acidize perms w/600 gallons 15% NEFE acid., swab. TIH w/ 2 3/8" 4.7#, J-55 prod tbg to 3984'. Run rods and pmp, space out, hang on. Turn over to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

[Signature] TITLE Drilling Tech. Asst. DATE July 12, 1988

APPROVED BY _____ TITLE _____ DATE _____
 REVISIONS OF APPROVAL, IF ANY: _____