

Submit 3 Copies
 to Appropriate
 District Office

State of New Mexico
 Energy, Minerals and Natural Resources Department
OIL CONSERVATION DIVISION
 P.O. Box 2088
 Santa Fe, New Mexico 87504-2088

Form O-102
 Revised 1-1-88

DISTRICT I
 P.O. Box 1080 Hobbs, NM 88240
DISTRICT II
 P.O. Drawer 60, Artesia, NM 88210
DISTRICT III
 1000 Rio Bravo Rd., Aztec, Nm 87413

API NO. assigned by OGD on New Wells 30-025-04428	
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>	
6. State Oil & Gas Lease No. NA	
7. Lease Name or Unit Agreement Name EUNICE MONUMENT SOUTH UNIT	
8. Well No. 142	
9. Pool name or Widestat EUNICE MONUMENT G/SA	
10. Elevation (Show whether OF, RKB, RT, GR, etc.) 3547' GL	

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" FORM O-101) FOR SUCH PROPOSALS.)

1. Type of Well:
 OIL WELL GAS WELL OTHER

2. Name of Operator:
CHEVRON U.S.A. INC.

3. Address of Operator:
P.O. BOX 1150 ATTN: RORY MATTHEWS

4. Well Location:
 Unit Letter **E** Section **36** Township **20S** Range **36E** Line and **660** feet From The **NORTH** Line **WEST** Line
 County **NMPV**

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTER CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABAN. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CMT JOB <input type="checkbox"/>	
OTHER: ADD PERFS & ACDZ <input checked="" type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work; SEE RULE 1103.)

MIRU, POOH WITH PRODUCTION TBG.
 CLEAN OUT WELL TO 4060'. PERFORATE W/ 3 JHPF, 0.5" GUNS, 120 DEG. PHSD AT 4064'-4068', 4052'-52, 3870'-3888', 3725'-3740'.
 SELECTIVELY ACIDIZE PERFS WITH 15,500 GALS. OF 15% HCL, SWAB BACK AND TEST.
 RETURN WELL TO PRODUCTION.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *Rory Matthews* TITLE DRILLING TECH. DATE: 6-20-95

TYPE OR PRINT NAME RORY MATTHEWS TELEPHONE NO. (915) 687-7812

APPROVED BY [Signature] TITLE ADVISOR DATE JUN 23 1995

CONDITIONS OF APPROVAL IF ANY

RECEIVED
JUN 22 1965
COURT HOUSE
OFFICE