

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-025-05551

5. Indicate Type of Lease
STATE FEE

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name
East Eumont Unit
008598

1. Type of Well:
OIL WELL GAS WELL OTHER Injection

8. Well No. 12

2. Name of Operator
OXY USA Inc. 16696

9. Foot name or Wildcat
Eumont Yates 7 Rvr Qn 022800

3. Address of Operator
P.O. Box 50250 Midland, TX 79710-0250

4. Well Location
Unit Letter C : 273 Feet From The North Line and 2400 Feet From The West Line

Section 4 Township 19S Range 37E NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3708'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

EAST EUMONT UNIT #12

MIRU PU 4/14/98, NDWH, NUBOP. REL PKR & POOH W/ TBG & PKR. RIH & SET CIBP @ 3580', LOAD HOLE W/ 10# MLF. DUMP 10sx CL C CMT TO 3484', POOH TO 3140'. SPOT 25sx CL C CMT TO 2899', POOH TO 2869'. SPOT 25sx CL C CMT TO 2628', POOH TO 2550'. SPOT 25sx CL C CMT TO 2309', POOH TO 1660'. SPOT 25sx CL C CMT TO 1395', POOH TO 300'. SPOT 25sx CL C CMT TO 60', POOH, ND BOP. SPOT 10sx CL C CMT SURFACE PLUG. RDPV 4/15/98, DUG OUT CELLAR, INSTALL DRY HOLE MARKER. NMOCD NOTIFIED BUT DID NOT WITNESS.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.
SIGNATURE David Stewart TITLE Regulatory Analyst DATE 7/8/98
TYPE OR PRINT NAME David Stewart

TELEPHONE NO. 9156855717

(This space for State Use)
APPROVED BY Johnny Robinson TITLE _____ DATE _____
CONDITIONS OF APPROVAL IF ANY:

JCS-H1112

103