

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

New Mexico Oil Conservation

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT --" for such proposals

5. Lease Designation and Serial No.
LC-034075

6. If Indian, Alottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and Number
North Monument G/SA Unit Blk. 2

Well 15

9. API Well No.
30-025-05634

10. Field and Pool, Exploratory Area
Eunice Monument G/SA

11. County or Parish, State
Lea County, New Mexico

SUBMIT IN TRIPLICATE

1. Type of Well: ☒ OIL WELL ☐ GAS WELL ☐ OTHER

2. Name of Operator
Amerada Hess Corporation

3. Address and Telephone N P.O. Box 840, Seminole, TX 79360 915-758-6778

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
Unit Letter O : 660 Feet From The South Line and 1980 Feet From The
East Line Section 18 Township 019S Range 037E

12. Check Appropriate Box(s) To Indicate Nature of Notice, Report, or Other Data

TYPE OF SUBMISSION

TYPE OF ACTION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ OTHER:

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☒ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log Form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true verticle depths for all markers and zones pertinent to this

Please refer NMOCD Division Order No. R-9596-A

Plan to MIRU pulling unit & TOH w/rods & pump. Remove wellhead, install BOP & TOH w/tbg. TIH w/6-1/8" bit & clean out fill to 3924'. TIH w/RBP set at 3760' & press. test csg. to 700 PSI. Install injection wellhead. TIH, latch onto & TOH w/RBP. Acidize perms. fr. 3810' - 3863' & Open Hole fr. 3875' - 3924' w/2000 gal. 15% NEFE acid. Swab load. If unable to swab fluid level down: drill out cement plug to 3935' & spot 5 sks. Class "H" cement fr. 3935' - 3917'. Swab to determine isolation. Drill out & re-spot larger plug if necessary. TIH w/pkr. on injection tbg. & set pkr. at +/- 3760'. Begin injecting water.

SUBJECT TO
LIKE APPROVAL
BY STATE

14. I hereby certify that the foregoing is true and correct.

SIGNATURE Roy L. Wheeler, Jr. TITLE Bus. Svc. Spec. II

DATE 12/20/2000

TYPE OR PRINT NAME Roy L. Wheeler, Jr.

(This space for Federal or State office use)

APPROVED BY ORIG. SGD.) LES BABYAK TITLE PETROLEUM ENGINEER

DATE JAN 17 2001

CONDITIONS OF APPROVAL, IF ANY:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

GW